

Queensland Floods Commission of Inquiry

CROWN LAW-(DERM – Peter Allen)
Response to Requirement Ref# 1674479
SMs # 1718862 (Signed) #1719064 (Unsigned)
Attach PHA 18 & 19 #1847881
File 535884/1
Volume 1 ORIGINAL

Statement of Peter Hugh Allen

September 2011
Vol 1

QFCI

Date:

10/2/12

Exhibit Number:

1128

**QUEENSLAND FLOODS
COMMISSION OF INQUIRY**

STATEMENT OF PETER HUGH ALLEN

I, **PETER HUGH ALLEN**, of c/- 41, George Street, Brisbane in the State of Queensland, Project Director (Dam Safety), Office of the Water Supply Regulator, Department of Environment and Resource Management, state on oath:

Requirement from Queensland Floods Commission of Inquiry

1. I have seen a copy of a letter dated 23 August 2011, which is attachment **PHA-18**, from the Commissioner, Queensland Floods Commission of Inquiry (the Commission) to me requiring a written statement under oath or affirmation, and which details the topics my statement should cover.
2. I have previously provided statements to the Commission dated 4 April 2011, an addendum to it dated 11 April 2011 and a supplementary statement dated 13 May 2011.

Role

3. My substantive position is the Director, Dam Safety (Water Supply) in the Office of the Water Supply Regulator, Environment and Natural Resource Regulation division, Operations and Environmental Regulator business group, Department of Environment and Resource Management (DERM). For the duration of the Commission of Inquiry I have been moved to a temporary position entitled "Project Director, Dam Safety". This was done as it was considered that I could not be expected to both perform the duties of the Director, Dam Safety as well as assist the Commission of Inquiry. Mr Norman John McKenna is currently the A/Director, Dam Safety until the Commission of Inquiry no longer requires my assistance. I will then resume my substantive position. Mr McKenna is not an engineer.

Item 1: The general process of review by Department of Environment and Resource Management officers of flood event reports submitted by operators of referable dams.

4. Two types of 'flood event reports' need to be submitted to DERM by the owners (not operators) of referable dams following a flood event and the general process of reviewing them will differ depending on the type of report required to be submitted.
5. **The owners of all referable dams** have a requirement to produce a flood event report if their Emergency Action Plan (EAP) is triggered during a flood event. If it is not triggered, NO flood event report is required. It should be noted that there are no legislative requirements regarding EAP's and they are not approved by

DERM's Dam Safety unit. Chapter 9 of the Queensland Dam Safety Management Guidelines sets out what should be in an EAP. Based on that the dam owner of a referable dam drafts an EAP and submits it to the Dam Safety unit for information.

This requirement is a result of the dam safety condition applied to the owners of all referable dams. Typically the current dam safety condition DS13 deals with Emergency Action Plans and Event Reports. Part 10 of DS13 would typically contain the following provision:

10. Within thirty (30) days of the event the Dam Owner must prepare an Emergency Event Report and provide a copy of the report to the Dam Safety Regulator. The Emergency Event Report must include:

- a. A description of the event.*
- b. Instrumentation readings (where appropriate).*
- c. Description of any observed damage.*
- d. Photographs.*
- e. Details of communication and actions which took place during the emergency.*
- f. How the EAP was implemented during the event and comment on the adequacy of the EAP and any changes proposed.*

6. This part of DS13 is primarily about reporting the performance of the dam during the flood event from a dam safety perspective. It is not so much about assessing the downstream flood impacts of normal spillway discharges and is primarily imposed to cover extreme flood events where the safety of the dam might be at risk.
7. Not all referable dam owners trigger their EAPs at the same time. Some referable dam owners only trigger their EAPs for extreme events while others trigger them for more frequent events. Additionally, the duration of flood events at dams can be quite variable so that the timing requirement for the submission of the report can be difficult to determine. This is especially the case when no automatic discharge gauging is available on inflows or outflows (although most major dams at least have manually read staff gauges). Flood events for dams with smaller catchments tend to finish sooner while larger catchment dams can run much longer. For instance, as reported in the press, Burdekin Falls Dam with a catchment of 114,000 km² flowed over the spillway this year for a reported 321 days.
8. There is no formal set work procedure for reviewing these flood event reports. It is likely to be different for different dams and will depend very much on the magnitude of the event and the consequences of the event. The following is the process adopted for the 2010-2011 wet season:
 - a) Firstly, it had to be determined whether the EAP had been triggered to determine whether there was a requirement for an event report. This was done through direct contact with 30 dam owners either via email or by telephone. (Theoretically, under part 9 of DS13 it is a requirement that the Dam Safety Regulator be notified within 48 hours that the EAP has been triggered but this is done inconsistently. However, from a practical perspective once the EAP is triggered it is far more important that any necessary warnings be issued and

inspections be undertaken to ensure the dam is operating satisfactorily than it is to notify the Director, Dam Safety (in Brisbane) who, being remote to the dam location, will probably not play a part in the emergency response and is not in a position to directly assist.)

- b) Once Dam Safety, DERM determined that the EAP had been triggered, it was noted and the dam owner was reminded of the need to produce an event report.
 - c) Dam Safety staff then followed this up to ensure that the flood event report was submitted. There were 24 EAPs activated as a result of the 2011 floods. The EAP event reports are at attachment **PHA-19**.
 - d) Once submitted, a dam safety engineer reviewed the report and advised the Director Dam Safety if there was a need for follow-up activity. As far as I am aware, there were no reports of serious damage to any dam other than in the Wivenhoe Dam spillway chute.
 - e) The follow-up action would have depended on the issue. For instance, if there were reports of damage, a Special Inspection under dam safety condition DS9 may have been required. If there were reports of difficulty with the EAP, Emergency Management Queensland could have been asked to assist.
 - f) However, for the 2010-2011 wet season, there was only one report of significant damage. This was the report of erosion in the Wivenhoe Dam spillway chute. I was notified of the erosion at 5:30 am on 19 January 2011 and I immediately arranged for one of the engineers from my Dam Safety group (Russ McConnell who had a role in the original design of the dam) to attend the inspection of the spillway chute by Seqwater that morning. Mr McConnell's report on that inspection, the associated incident report and the final Seqwater report are attached as **PHA-20**.
 - g) While the DERM Dam Safety group is well qualified to address dam safety issues, the same is not the case for EAPs. This is really the domain of the Local Disaster Management Group and the Commission of Inquiry's recommendation 4.15 concerning the attendance of referable dam owners at Local Disaster Management meetings should significantly improve coordination of the Local Counter Disaster Management Plans and EAPs.
9. The owners of referable dams having flood mitigation manuals under the provisions of the *Water Supply (Safety and Reliability) Act 2008* are also required to produce flood event reports. This requirement is detailed in the flood mitigation manual and is triggered whenever there are flood releases from the dams. The flood mitigation manual flood event report is essentially in addition to the DS13 requirements and means that a much more comprehensive report is produced.
10. As stated in paragraph 26 of my Statement of 4 April 2011, currently this requirement only applies to Wivenhoe, Somerset and North Pine dams.

11. Again, there is no set work procedure for reviewing flood mitigation manual flood event reports because I have not previously reviewed any major flood event reports for Wivenhoe, Somerset or North Pine dams. This is because there have been no major flood events that have required significant spillway discharges from these dams since the February March 1999 flood events (I did not review the 1999 flood event report because as I was working in the Flood Operations Centre during the event there would have been a perceived conflict of interest). For instance, the previous May to July 2009 flood events which had a peak discharge from Somerset Dam of 875 m³/sec and no significant discharge from Wivenhoe Dam, had a much more concise flood event report. Because of the infrequency and magnitude of flooding events over the last 12 years, no set work procedure has been developed for reviewing flood mitigation manual flood event reports.

Item 2: The specific process of review undertaken by DERM officers of the flood event reports produced by Seqwater regarding the January 2011 flood event at Wivenhoe, Somerset and North Pine dams

12. The specific process of reviewing the Seqwater January 2011 flood event reports for Wivenhoe, Somerset and North Pine Dams is detailed below.

Wivenhoe and Somerset Dams

- a) DERM received the Wivenhoe/Somerset flood event report at 4pm on 2 March 2011. This was the due date specified in the Manual.
At this time, I was already aware of Mr Brian Cooper's review (Cooper, January 2011) conducted on behalf of the South East Queensland Water Grid Manager of the flood operations during the January floods which concluded that "*...The strategies in the Flood Mitigation Manual have been followed, allowing for the discretion given to make variations in order to maximise flood mitigation effects. The actions taken and decisions made during the Flood Event appear to have been prudent and appropriate in the context of the available knowledge available to these responsible for flood operations and the way events unfolded...*" (p.3 of Mr Cooper's final report).
I was also advised by a number of Seqwater officers that Seqwater had arranged for a number of internal reviews of the report prior to submission to DERM. However, I have not seen the results of these internal reviews. I understand they were provided to the Commission of Inquiry.
- b) Once the Wivenhoe/Somerset flood event report was received, I made a brief examination of it myself (which did not reveal any major deficiencies or errors) and a copy was provided by the then Director-General, DERM to the Commission on 2 March 2011. It was also placed on the DERM internet website.
- c) Given the interest in the flood operations, I then developed an EXCEL spreadsheet model to examine gate operations. This spreadsheet has been used to examine how Somerset and Wivenhoe dams would have been operated for a whole range of historical and design floods with a view to examining potential future variations to the FMM. Some of the results of this

modelling were contained in the Commission of Inquiry's Exhibit 400.

- d) I started my review of the performance of Wivenhoe Dam soon after the submission of the Seqwater flood event report and it has been ongoing. As part of this process, the Office of the Water Supply Regulator (OWSR) engaged an independent engineer, Mr David Murray from engineering company, SMEC, to participate in and observe the review so that he could provide an independent assessment if needed. This process has not yet been completed.
- e) I am aware that the Commission of Inquiry has engaged its own consultants (such as Mark Babister) to comment on different aspects of the flood operations and I am aware of the reports that they have produced. In particular, I note Mr Babister's (WMA Water, 2011) comments in his report to the Commission. This tends to support the view that the procedures already in the existing manuals worked tolerably well during the January 2011 flood event.
- f) In addition to these, I have also undertaken a number of relatively simple assessments of the performance of the Wivenhoe/Somerset dams and their ability to pass a range of design flood events and historical flood events. In addition to this, I have also examined options for reducing the Wivenhoe Dam Full Supply Level from EL 67.0 mAHD to EL 64.0 mAHD following the 'Late December' flood event.

The outcomes of these analyses are attached as follows:

PHA-17	Document provided to the Commission as Exhibit 400 during my appearance before the Commission on 17 May 2011.
PHA-21	Examining the potential drawdown of Wivenhoe Dam following the Late December 2010 flood event


- g) Due to my ongoing dealings with this Commission of Inquiry and in implementing the recommendations contained in the Interim Report, I have not had sufficient time to devote to my detailed review of the report and therefore I have been unable to draw specific conclusions on the adequacy of the January 2011 flood operations and of compliance with the Flood Mitigation Manual. It is also unlikely that the current commitments that I have in reviewing the Interim Flood Manuals will permit finalising this review in the near future.
- h) I have also taken note of the comments on the flood operations and the flood mitigation manual during the Commission hearings and the recommendations made in the Commission's Interim Report.
- i) The reality now is that no previous flood event report has ever been the subject of greater review or comment.

North Pine Dam

The process for the review of the North Pine Dam flood event report was as follows:

- (a) While preparing their flood event report, Seqwater identified a number of issues relating to the performance of the dam which raised questions about the current understanding of design flood hydrology for North Pine Dam. These were discussed in paragraphs 149 to 151 of my Statement of 4 April 2011.
- (b) On the morning of 18 May 2011, there was a meeting held between Seqwater and DERM to discuss the apparent shortcomings of the performance of the dam during the January 2011 flood event. The outcomes of this meeting were confirmed in an email that I sent to Jim Pruss of Seqwater that afternoon which is attachment **PHA-22**.
- (c) Seqwater then engaged consultants URS to undertake a review of the performance of the dam during the January 2011 flood event.
- (d) DERM received the North Pine Dam flood event report at 11:30am on 31 May 2011. Seqwater was originally required to submit their report within six weeks of the flood event. However, the then Director General, DERM granted Seqwater an extension to 31 May 2011 due to the workload Seqwater was experiencing on dam safety and flood mitigation issues at the time.
- (e) The then Director General, DERM provided a copy of the report to the Queensland Floods Commission of Inquiry on 1 June 2011. It was also placed on the DERM internet website.
- (f) I prepared a spreadsheet to examine the performance of North Pine Dam during the January 2011 event. This allowed me to make a comparison between the actual operations of North Pine Dam and the way it might have operated if the minimum gate openings specified in the flood mitigation manual had been applied. The results of this analysis are summarised below. In comparing these results it is important to note that the way the dam was actually operated during the flood event produced lower discharges than might have resulted if the minimum gate openings had been applied.

January 2011 - Comparison of Discharges



In summary, this figure indicates:

- i. Early in the event, there were greater releases than the target gate openings nominated in the manual. This effectively held the storage levels lower for longer while the event was building and it would have had a similar effect as a pre-release.
 - ii. Later in the event as headwater levels were rising, discharges were in accordance with the target gates openings for most of the rising limb. However, when the headwater level rose to about EL 40.6 mAHD, there was a brief period when the operators appear to have had some difficulty keeping up with the target gate openings.
 - iii. On the falling limb, the discharges were higher than the targets but that was probably appropriate given the problems that had occurred during the peak of the flood.
- (g) The Dam Safety group has received several reports from Seqwater on the studies being carried out by consultants URS (who are reviewing the North Pine Dam hydrology on the behalf of Seqwater). The reports include:

PHA-23	Memo from URS to Seqwater 12 May 2011 re: North Pine Dam – Spillway rating curve assessment
	Memo from URS to Seqwater re: North Pine Dam – Spillway Bridge and Radial Gates Preliminary Structural Evaluation
	Memo from URS to Seqwater re: North Pine Dam Acceptable Flood Capacity Review by URS
	Memo from URS to Seqwater 19 June 2011 re: Review of the North Pine Dam Storage Rating Curve
	Memo from URS to Seqwater re: Detailed Review of 11 January 2011 Rainfall
	Interim Draft Report on North Pine Dam Spillway Flood Capacity Assessment - Mechanical

- (h) The final results of this study are expected by early September 2011. Ultimately the outcomes of the URS studies will inform actions which might be necessary in relation to North Pine Dam.

Item 3: The assessment and opinion of the DERM officer as to the flood event reports produced by Seqwater regarding the January 2011 flood event at Wivenhoe, Somerset and North Pine dams (any relevant correspondence or other documents should be attached)

Wivenhoe and Somerset Dams

13. The Wivenhoe/Somerset dams report was quite comprehensive in terms of what was contained in it and in the extent of the detail that Seqwater has provided on the event. The quality of the report is far in excess of that which I put together

following the 1999 flood events which in itself was far more comprehensive than any previous report. In my opinion Seqwater were quite open as to how they operated the dams.

14. I have given some comment on the adequacy of the flood operations in Item 2.

North Pine Dam

15. The North Pine Dam report was also quite comprehensive in terms of what was contained in it and in the extent of the detail that Seqwater has provided on the event.

16. The report also highlighted deficiencies identified in the flood hydrology for North Pine and enabled these deficiencies to be suitably addressed prior to the 2011-2012 wet season.

Item 4: Any action taken by any DERM officer as a result of the review of the flood event reports produced by Seqwater regarding the January 2011 flood event at Wivenhoe, Somerset and North Pine dams

Wivenhoe and Somerset Dams

17. As stated above, the OWSR Dam Safety review of this report has not been completed. However, as indicated above, these reports have been the subject of extensive review by others including the Commission of Inquiry. Action has been considered but to date has been found unnecessary as the Commission of Inquiry interim report has dealt with all necessary actions.

North Pine Dam

18. Paragraph 150 of my Statement dated 4 April 2011 noted that discussions had been held with Seqwater and that Seqwater were to prepare a program of works to be undertaken to remedy the identified problems referred to in Item 2 above. Since then the following actions have been taken by me and other DERM officers:

- Spreadsheet modelling looking at performance of gate operations during the January 2011 event (refer to Item 2).
- Monitoring reports from URS via Seqwater on the North Pine Dam hydrology review.

Item 5: A detailed description of the current process for the consideration, review and approval of flood mitigation manuals under the Water Supply (Safety and Reliability) Act 2008(Qld), including:

19. A distinction needs to be made between the person who approves the Manual (approver) as opposed to the person who assesses the Manual (assessor). The assessor reviews a Manual which is provided to DERM by the dam owner to assess whether it meets DERM's requirements for a manual. Technically speaking, however, one person can assume both roles.

20. Under Section 371 (2) of the *Water Supply (Safety and Reliability) Act 2008* the chief executive may by gazette notice, approve the manual. The chief executive has delegated the authority to approve the manuals under the *Water Supply (Chief Executive) Delegation (No.1) 2011 (PHA-23a)* to the holders of four (4) offices within the Department. I am the holder of one of the offices. In the past I have approved Revisions 5, 6 and 7 of the Wivenhoe and Somerset Manual and Revisions 4 and 5 of the North Pine Manual. I have acted as the assessor for various Revisions of the Wivenhoe and Somerset Manual and the North Pine Manual. For the current short term review and long term review of both Manuals I will be the assessor. I believe it is currently intended that the Director-General will be the approver of both the amended Manuals.

1. how it is determined who will assess the Manual

21. I determine who will assess the manuals within the Dam Safety group. The reality though is that Ron Guppy and I are the only persons in the group who have the necessary expertise to undertake such an assessment.
22. The manuals will also be assessed/reviewed by DERM lawyers.

2. how, if at all, the assessor would be involved in the preparation of the manual for submission by the operator

23. Neither Ron Guppy nor I have been involved in the preparation of a Manual. However, we have both in the past had a limited involvement in the review of the manuals before they were formally submitted by the dam owner (not operator) to DERM for approval. In the past we have attended meetings with Seqwater staff when discussing changes to be made to the manuals. Such meetings were designed to ensure that there was a common understanding of what was said or implied in the manual. We also provide advice on such things as what needed to be included in the manuals. The content of the manuals and what was submitted for approval remained at the complete control of Seqwater. In the past when a manual has been submitted for approval we do not accept it without question and still subject the manual to a rigorous assessment.
24. The process for approval of both manuals will be in accordance with the OWSR DERM work procedures for the consideration of the Flood Mitigation Manuals. At the time of the initial Commission of Inquiry hearings this was procedure DS 5.1. However, as indicated in Item 6 below, following our review of the work procedure, this has been renumbered and the relevant procedure is now DS 5.3.
25. Given the extremely short time frame that is available to have the Interim Flood Manuals ready for the 2011-12 wet season, it is important that the action officers of DS 5.3 liaise directly with Seqwater and get some prior agreement on what should be included in the version submitted for approval. This will maximise the chance that they will be approved before 1 October 2011.
26. Seqwater submitted their initial draft of the Interim Manual to DERM for comment on 19th August 2011. DERM Dam Safety and Legal Services officers

undertook an initial review of the draft manual and provided comments back to Seqwater at a meeting on 26th August 2011.

27. Seqwater agreed to consider the issues/amendments raised and for particular issues to be resolved out of session by myself and John Tibaldi (of Seqwater). I agreed to meet John Tibaldi at the new Flood Operations Centre (in 340 Adelaide Street, Brisbane) on 30th August 2011. I also involved Ron Guppy of my group in these discussions.
 28. Seqwater provided an update of the draft Interim Somerset/Wivenhoe Manual to DERM on 2 September 2011.
 29. It was indicated that Seqwater had considered our comments in generating this version of the Manual.
 30. A further up-dated version was received on 7 September 2011. Negotiations are continuing.
- 3. in what circumstances, if any, advice would be sought from an advisory council under s 371(4) Water Supply (Safety and Reliability) Act 2008 (Qld)**
31. The initial draft of the revised North Pine Dam Manual was received from Seqwater on 7 September 2011. It is currently being reviewed.
 32. Section 371(4) of the *Water Supply (Safety & Reliability) Act* enables the chief executive to get advice from an advisory council before approving the manual. However, the mechanism for establishing an advisory council is contained in section 570 of the Act. It provides that the Minister (not the chief executive) may establish advisory councils as the Minister considers appropriate for the administration of the Act including, for example (a) flood mitigation (b) referable dams. The advisory council is to have the functions the Minister decides.
 33. If the chief executive decided advice from an advisory council was necessary, the chief executive would have to request the Minister to establish such a council.
 34. In my opinion, the chief executive would only seek advice from such an advisory council if there were issues that could not be resolved satisfactorily either within DERM or between DERM and Seqwater. However, that is a decision for the chief executive.
 35. As stated in paragraph 28 of my Statement dated 4 April 2011, no advisory panel has been established since the commencement of the *Water Act 2000*.
- 4. in what circumstances, if any, an expert independent peer review would be obtained**
36. In my opinion, an independent peer review panel might be engaged by DERM if there were issues that could not be resolved satisfactorily either within DERM or between DERM and Seqwater.

5. the involvement of the Director-General in the review of the Manual

37. That is entirely up to the Director General.
38. However, to the best of my knowledge no previous Director-General has been directly involved in the review of a manual.
39. Prior to the *Water Act 2000*, the flood mitigation manuals were approved by the Minister. The Director-General (or the Commissioner of Water Resources when the function was the role of the Queensland Water Resources Commission) would have had to endorse any briefing note to the Minister to approve the Manuals.

Item 6: A description of any review or redrafting of the DERM publication DS 5.1 Flood mitigation manual for a dam since 1 January 2011, or any planned review or redrafting (any relevant correspondence or other documents should be attached)

40. The DERM work procedures addressing flood mitigation manuals have been extensively reviewed and updated to take into account the Interim report recommendations of the Queensland Floods Commission of Inquiry and the lessons learnt from events of January 2011. It is expected that a further review may be required to incorporate any further suggested changes recommended in the final report of this Commission of Inquiry.
41. The current review has been conducted within the Office of the Water Supply Regulator with assistance from departmental lawyers. These are general work procedures which do not require regulatory approval.
42. It is expected that DS 5.3 will be approved and ready for use to assess the Interim Flood Mitigation Manuals for Wivenhoe/Somerset and North Pine Dams which are due to be submitted to DERM in mid-September 2011. The main changes to the previous version were:

- a. a reordering of the work procedures. The new numbering is as follows:

DS5.1	When a manual is required to be written and submitted for a dam that has just been listed in a regulation as requiring a flood mitigation manual (s.371)
DS 5.2	When the chief executive directs the owner of a dam already having a flood mitigation manual to make particular amendments to the existing manual (s.372)
DS 5.3	When a flood mitigation manual is reviewed so that the reviewed manual can replace an existing manual. It effectively replicates the equivalent provisions in DS 5.1. (This work procedure will therefore apply to the approvals of the Interim North Pine Dam and Somerset/Wivenhoe Dam Manuals.)

- b. allowance for the direct approval of the Manuals by the chief executive.

- c. provision for greater documentation of the review of the manual by DERM and the decision by the decision maker
 - d. provision for legal review of the manual if required
 - e. provision for a more detailed examination of the decision making process
 - f. Each work procedure was written as a stand-alone document so that it could be used independently of the others.
43. Overall, work procedure DS 5.3 requirements are more specific than the previous version and provide for a more robust, better documented procedure for the approval of the flood mitigation manuals. A copy of the new work practice DS 5.3 (subject to internal approval for use within OWSR) is attached as **PHA-24**.

Item 7: A detailed description of the specific process of consideration, review and approval of the flood mitigation manuals for Wivenhoe and Somerset Dams (Seventh Revision, 2009) and North Pine Dam (Fifth Revision, 2010), including all reasoning and opinions and attaching all relevant documents created during the process of consideration and approval

44. A copy of documentation for the decision approving Revision 7 - Wivenhoe and Somerset Dams Flood Mitigation Manual was attached to my 4 April 2011 Statement as **PHA-06**.
45. A copy of Seqwater notes on the amendments made to produce Revision 7 was also attached to my 4 April 2011 Statement as **PHA-07**.
46. Additional copies of correspondence and documents for Revision 7 of the Wivenhoe and Somerset Dams Flood Mitigation Manual are attached to this statement as **PHA-25**.
47. Copies of the same documents for Revision 5 of the North Pine Dam Flood Mitigation Manual are attached to this statement as **PHA-26**.

Item 8: In particular, an explanation of why certain amendments (including those outlined in the table comprising Exhibit 399 of the Queensland Floods Commission of Inquiry) suggested by Mr Ron Guppy with respect to the Seventh Revision of the Wivenhoe and Somerset Dams flood mitigation manual were not required of Seqwater prior to approval of the flood mitigation manual submitted

48. In general terms, Revision 7 of the manual for Wivenhoe and Somerset dams was the first attempt to introduce 'predicted' levels and discharges into the gate operating strategies. While Revision 6 had been based on actual headwater levels, there were predictions of downstream flow rates in the Lockyer and the Bremer applied when determining the actual releases within a strategy.
49. The comments made by Mr Ron Guppy relate to the introduction of these headwater predictions. A table comparing comments made by DERM and sent to Seqwater by e-mail dated 13 October 2009 (Annexure 18 and 19 to Statement of

Ronald Guppy) that were not incorporated into final version of the Seventh Revision of Wivenhoe/Somerset Flood Mitigation Manual and which includes my response is attached as **PHA-27**.

Item 9: Opinion as to any suggested change to the process of consideration, review and approval of flood mitigation manuals

50. As stated in Item 6 above, the work procedures for consideration, review and approval of revised flood mitigation manuals have already been significantly reviewed to make the decisions more robust and better documented. The Commission of Inquiry recommendations for an interim review of the manual and a longer term review of the manuals have also been adopted.
51. Any further recommendations made by the Commission of Inquiry will also be seriously considered.

Item 10: an account of actions taken by officers of DERM in response to the endorsement of the briefing note provided to the Honourable Stephen Robertson MP, Minister for Natural Resources, Mines and Energy and Minister for Trade on 22 October 2010 (CTS No 19311/10); in particular, whether the draft letter under the hand of Mr Allen attached to the briefing note about confirmation of the currency of emergency action plans was in fact sent to the owners of large water supply dams (any relevant correspondence or other documents should be attached)

52. Further advice was provided to Minister Robertson on 15 November 2010 in CTS 19928/10 attached as **PHA-28**. This briefing note attached the details of what was being done. These actions included:

- a. Letters were sent to dam owners of 69 referable dams requiring written confirmation that the EAPs for these dams were current by 30 November 2010. Copies of these letters are also attached as **PHA-28**. These dams are listed below.

Dam Owner	Dams	
SunWater	Leslie Dam	Peter Faust Dam
	Bjelke-Petersen Dam	Tinaroo Falls Dam
	Boondooma Dam	Wuruma Dam
	Burdekin Falls Dam	Kroombit Dam
	Callide Dam	Teemburra Dam
	Cania Dam	Paradise Dam
	Coolmunda Dam	Woongarra Balancing Storage
	Eungella Dam	Moura Offstream Storage
	EJ Beardmore Dam	Isis Balancing Storage
	Fairbairn Dam	Claude Wharton Weir (not currently a referable dam)
	Fred Haigh Dam	
	Julius Dam	
	Kinchant Dam	
Queensland Bulk Water Supply Authority	Lake MacDonald Dam	Gold Creek Dam
	Atkinson Dam	Hinze Dam
	Baroon Pocket Dam	Lake Manchester Dam
	Bill Gunn Dam	Leslie Harrison Dam
	Borumba Dam	Poona Dam
	Cedar Pocket Dam	Wappa Dam
	Clarendon Dam	Bromelton Off-Stream Storage
	Cooloolabin Dam	

	Enoggera Dam Ewen Maddock Dam Little Nerang Dam Maroon Dam Moogerah Dam Sideling Creek Dam	Somerset Dam, Wivenhoe Dam, North Pine Dam (These three were not sent letters because of the Flood Mitigation Manuals)
DERM	Ibis Dam Copperfield R Gorge Dam	Corella Dam Crooks Dam Wyndham Dam
Others	Tallebudgera Creek Dam Connolly Dam Cooby Creek Dam Copperlode Falls Dam Cressbrook Creek Dam Lenthalls Dam Paluma Dam Perseverance Creek Dam Ross River Dam Theresa Creek Dam Biggera Creek Flood Detention Basin	Eli Creek Effluent Reuse Storage Dam Wild River Dam Splityard Creek Dam Koombooloomba Dam Loders Creek Flood Detention Basin Rosewood Detention Basin Marburg Detention Basin

- b. There are only really four (4) EAP's for the five (5) referable dams owned by DERM as the EAP for Wyndham Dam and Crooks Dam are combined into the one document.
- c. No letter was sent to the following referable dam owners:
- i. for nine dams, because the population at risk was confined to property owned by the dam owner and there was no downstream community that needed to be notified by the relevant local government or emergency management agency in an emergency situation;
 - o Bundoora Dam
 - o Gap Creek Dam
 - o Dashwood Property Dam
 - o Dalrymple Bay Coal Terminal – Quarry Dam
 - o Newlands Coal Mine – Cerito Creek Dam
 - o Cubbie Station – Top Shed Dam
 - o Russell Property Irrigation Dam
 - o Andrew Deguara Holdings Pty Ltd Dam
 - o South Walker Mine – Down Dip Dam
 - ii. the owners of a further 16 dams because the owners had already informed DERM within the previous four months that they had produced/updated or reviewed their EAPs.
- d. Additionally there were ten referable dams that had no EAPs because:
- i. safety condition DS 13 required an EAP to be prepared by 30/11/2010 (which was after the nominated reporting time) for Crystal Waters Estate (Upper and Lower) Dams;
 - ii. construction of Gillens Dam owned by Kupapipi Pastoral Pty Ltd had not yet commenced;
 - iii. Town Dam Lakeland owned by Cook Shire Council was to be modified so that it no longer had a population at risk and therefore will not require an EAP (this modification has now been completed and the updated Failure Impact Assessment for the dam to determine if it remains 'referable' is

- being considered); and
- iv. in the case of the seven referable dams listed below in Item 11, compliance action had been initiated as the dam owners have failed to produce their EAP by the date required.

The current status of Emergency Action Plans is listed in **PHA-29**.

Item 11: An account of any enforcement actions taken by officers of DERM in response to any non-compliance with the request to dam owners for confirmation as to the currency of emergency action plans. Such account should include an explanation as to why such enforcement actions were selected (any relevant correspondence or other documents should be attached)

53. As indicated above, compliance action was initiated against seven dam owners for failing to provide updates of the Emergency Action Plans. The following summarises communication/compliance action by the Dam Safety unit in respect of the seven dams:

2016 - Springfield Lakes - High Level Dam (has current EAP)

- a. 4/11/10 - email to dam owner enquiring about status of preparation of EAP
- b. 30/11/10 - email from dam owner advising draft EAP available for download on Water Solutions website
- c. 30/11/10 - Dam Safety downloaded draft EAP
- d. 13/03/11 - finalised EAP received in Dam Safety unit.

2277 Springfield Lakes - Low Level Dam (has current EAP)

- e. As above

1946 - Moody Creek Detention Dam (has current EAP)

- f. 13/12/10 - Dam Safety unit contacted dam owner's consultant who advised EAP to be prepared by January 2011
- g. 11/01/11 - Contacted dam owner's consultant - EAP preparation in progress, anticipate completion in next couple of weeks
- h. 20/01/11 - Contacted dam owner's consultant - EAP preparation in progress
- i. 21/02/11 - Contacted dam owner's consultant - draft EAP progress delayed by Cyclone Yasi
- j. 2/03/11 - Dam Safety unit asked dam owner if EAP activated following flood events in Qld from Dec 2010 onwards

- k. 8/03/11 - Dam owner unit advised EAP not activated as there had been no problems and no reason to activate EAP
- l. 18/03/11 - Dam Safety unit issues 'Show Cause Notice' on 18/03/11 - breach of safety/development condition for failure to submit EAP
- m. 9/05/11 - Dam Owner (Cairns Regional Council) advises consultant heavily involved in work for Qld Reconstruction Authority in Tully area since Cyclone Yasi. EAP for Moody Creek Detention Dam and EAP for McKinnon Creek Detention Dam (also owner by CRC) to be submitted by end May 2011
- n. 22/06/11 - EAP for Moody Creek received in Dam Safety unit

521 - Lake Mitchell Dam (has current EAP)

- o. 9/11/10 - email to dam owner's consultant seeking progress with EAP
- p. 22/12/10 - email from dam owner's consultant with electronic version of EAP attached

651 - Forest Lake Dam (has current EAP)

- q. 4/11/10 - email to dam owner requesting EAP by the end of November 2010
- r. 6/12/10 - email from dam owner advising EAP referred to key disaster management areas before final sign off and submission
- s. 23/12/10 - EAP for Forest Lake Dam received in Dam Safety unit

657 - Gordonbrook Dam (has Interim EAP only)

- t. 29/02/08 - Comprehensive Inspection report prepared by Worley Parsons in February 2008 noted no EAP for Gordonbrook Dam
- u. 28/09/10 - email to South Burnett Regional Council (SBRC) informing the council that Director, Dam Safety required acceptable EAP be ready for implementation before coming wet season - (meaning Nov/Dec 2010)
- v. 25/11/10 - email from SBRC advising consultants (Cardno) engaged to develop EAP for Gordonbrook Dam - final draft to be ready by end Dec 2010
- w. 22/12/10 - final draft of EAP submitted by SBRC
- x. 31/01/11 - email from DERM (Ken Nguyen) to SBRC advising that current draft EAP can be adopted as Interim EAP until SOP is finalised in Sept 2011 when Interim EAP can be reviewed and updated and submitted with SOP
- y. 19/07/11 - email to SBRC regarding status of Interim EAP
- z. Discussions are ongoing.

222 - Environment Dam (no EAP)

- aa. 8/11/1999 - Water Licence 38929F authorising Environmental Dam renewed to 31/01/2004 - included special conditions relating to dam safety including decommissioning the dam (Licence Term 5 - Schedule B)
 - bb. 14/11/07 - email to dam owner advising acceptance of Failure Impact Assessment for Environmental Dam on 13/11/2007 as category 1 referable dam (Population at Risk - 3) and that dam safety conditions will be applied to the dam
 - cc. 23/12/09 - safety conditions prepared including covering letter - no evidence that letter and conditions forwarded to dam owner
 - dd. 8/11/10 - email to dam owner providing a copy of the safety conditions dated January 2010 - DS13 required EAP to be prepared and submitted by 31/10/2010
 - ee. 8/11/10 - dam owner sends reply email advising that the company has no record of these documents in its site records
 - ff. 11/11/10 - email to dam owner advising that new safety conditions with revised dates for submission of EAP and other documents to be prepared
 - gg. 23/06/11 - email from dam owner applying to remove Environmental Dam embankment that is licensed under Water Licence 38929F. Application supported by Decommissioning Final Rehabilitation Plan prepared for dam owner by Water Solutions Pty Ltd
 - hh. 5/07/11 - email from Manager, ES - Mining, Emerald (Chris Loveday) to Kirsty Meacle, Snr Advisor, Regulatory Services, CW Region Rockhampton advising that OWSR doesn't have any concern about the proposed actions around decommissioning other than what is to be done with the water in the dam to allow decommissioning to occur
 - ii. 5/09/11 - email to Kirsty Meacle seeking update of proposal to decommission. Kirsty advised the dam owner will be asked to provide more information including explanation about how dam is to be dewatered.
54. The copies of all the referenced documents are contained in attachment PHA-30.

Item 12: If officers of DERM did not take any enforcement action in response to dam owners failing to provide assurances about the currency of emergency action plans, an account as to why enforcement action was not taken, and a description of any other action taken in response to failure to comply with the request to provide confirmation as to the currency of emergency action plans (any relevant correspondence or other documents should be attached).

55. The necessary compliance action is summarised in Item 11. There was no need to take further compliance action.

Item 13: An account, excepting matters addressed in his statement of 4 April 2011, of any other actions taken by officers of DERM relating to dam safety and flood mitigation issues for all or any referable dams and any other large water storage dams in Queensland in readiness for the 2010/2011 wet season (any relevant correspondence or other documents should be attached)

56. Under the provisions of the *Water Supply (Safety and Reliability) Act 2008*, DERM has no regulatory control over the safety of water dams that are not referable dams. As such, it has no control over 'other large water supply dams'.
57. Aside from the specific follow-up activity prior to the 2010-2011 wet season on Emergency Action Plans there has been a lot of ongoing dam safety activity to improve the safety of referable dams. This involves a wide range of activities such as identifying the dams that might put population at risk through to the periodic inspections, safety reviews etc. required by the dam safety conditions and audits to make sure that dam owners are aware of their responsibilities and audits to improve compliance.
58. Part of this ongoing process is the spillway adequacy program. In this program, DERM is targeting improvement in the spillway adequacy of all referable dams. The required upgrade schedule is set out in the *DERM Guidelines on Acceptable Flood Capacity for dams* (NRM, 2007). The spillway capacity of a number of dams has been increased since about 2004. These include:
- a. Tallebudgera Creek Dam
 - b. Fred Haigh Dam
 - c. Borumba Dam
 - d. Bjelke Petersen Dam
 - e. Wivenhoe Dam
 - f. Tinaroo Falls Dam
 - g. Crooks Dam
 - h. Wyndham Dam
 - i. Gold Creek Dam
 - j. Lake Manchester Dam
 - k. Hinze Dam (as part of an overall upgrade)
 - l. Ross River Dam (as part of other remedial works).
59. The spillway adequacy of Middle Creek Dam was improved just prior to the 2010-2011 wet season by the removal of a nib wall on the spillway crest. By doing this, the Mackay Regional Council was able to increase the spillway capacity from a totally inadequate 1:40 AEP flood event to a 1:500 AEP event. This was required under Dam Safety condition DS 16 for the dam. A further increase in capacity to 50% of the Acceptable Flood Capacity is required by October 2015.
60. The risks of failure of Storm Creek Dam and Kinchant Dam are being reduced by current works. Further information on each of these upgrades can be provided upon request.

61. Operationally, Townsville Regional Council who own Ross River Dam asked whether they could pre-release water from the dam prior to Cyclone Yasi. I had no objection to this pre-release from a dam safety perspective so long as the risks to people downstream were appropriately managed.
62. I am not aware of any other specific preparations by dam owners for the 2010/2011 wet season. From a dam safety perspective, referable dams need to be designed and constructed to a high standard and the design floods used for the design of the dam are far greater than any flooding that occurred over the 2010/2011 wet season.
63. Irrespective of the above, the safety of a dam remains the responsibility of the dam owner. The dam safety conditions applied by DERM are essentially the framework for an owner's effective dam safety management program.
64. I am not aware of any other actions that may have been taken by other DERM officers.

Item 14: Opinion as to any suggested change to the relationship between the flood operations centre in control of Wivenhoe and Somerset dams and the operators of the Splityard Creek dam to increase efficiency of operating all three dams and flood mitigation benefits provided by those dams


65. Given that the total volume of Splityard Creek Dam translates to about 1% of the January 2011 flood event which passed through Wivenhoe Dam, I do not see any necessity to change the relationship between the flood operations centre and the operators of Splityard Creek Dam as I do not consider that it will result in any significant increased flood mitigation efficiency in major floods.
66. The operating range of Splityard Creek Dam is of the order of 28,700 ML. The pumping time to fill this storage from empty is 14 hours and the generating time to drain the storage from full is 10 hours. Thus if all this volume is added to, or taken from, Wivenhoe Dam this translates to the following rises and falls in Wivenhoe Dam:

Headwater level in Wivenhoe mAHD	Rate of increase in Wivenhoe level during generating	Rate of decrease in Wivenhoe level during pumping	Total variation over cycle
EL 67.0	27 mm/hr	19 mm/hr	± 270 mm
EL 74.0	19 mm/hr	13 mm/hr	± 190 mm
EL 80.0	14 mm/hr	10 mm/hr	± 140 mm

67. On top of this examination of the available headwater levels in Splityard Creek Dam over the period from 7 October 2010 to 28 August 2011 indicate that:
- On only about 20% of days is more than 2000 ML pumped into or drained out of Splityard Creek Dam
 - The maximum pumped into or drained out of Splityard Creek Dam over the

period was about 7,500 ML or about 25% of the total available storage.

68. As such, Splityard Creek Dam cannot have much effect on flood mitigation for areas downstream of Wivenhoe Dam. The graph below shows the volume of water pumped or used for power generation between 7 October 2010 and 28 August 2011.



69. However, a rise or fall of about 270mm near Full Supply Level of Wivenhoe Dam can have a significant effect if Wivenhoe is operating in strategy W1 or during the final drainage phase. This occurred during the drainage phase of the February 1999 flood event when I was the Senior Flood Operations Engineer for the event and it caused problems until what was causing the unexpected rise and fall in the reservoir was identified.
70. The Flood Event Report for the February 1999 flood event recommended (in Section 18.5 of SWP, 1999) that a headwater gauge be installed to measure headwater elevations in Splityard Creek Dam to enable Wivenhoe headwaters to be adjusted for the volume stored in Splityard. This recommendation was implemented by the then South East Queensland Water Board.
71. Splityard Dam was not discussed in the Seqwater January 2011 flood event report for Wivenhoe and Somerset dams.

Item 15: In particular, in what circumstances it would be beneficial for the flood operations centre in control of Wivenhoe and Somerset dams to have control over releases from Splityard Creek dam and pumping of water from Wivenhoe dam into Splityard Creek dam

72. As it stands, there seems to be a good working relationship between Seqwater and the operators of the Wivenhoe Power Station. While this relationship remains good, there should be no need for any direct control over the levels in Splityard Creek Dam. However, this may not always be the case.

73. The circumstances that I can foresee where there might be a role for the flood operations centre to have some control over the releases from Splityard Creek dam and pumping of water from Wivenhoe dam into Splityard Creek dam would be when:
- a. drainage of water from Splityard Creek Dam might trigger a fuse plug or cause overtopping of the dam or overtopping of the gates; or when
 - b. pumping of water into Splityard Creek Dam might reduce the headwater level in Wivenhoe just enough to prevent such events occurring.
74. These should be rare events with the headwater level in Wivenhoe Dam only being expected to exceed EL 74 on average about once in every 50 to 100 years with the current operating rules.
75. There is of course a significant limit to what can be achieved using Splityard Creek Dam and the Flood Operators Engineers might also need to ensure that the storage is relatively low at the start of an event or, if it has significant volumes already in storage that it is drained in the early part of the event when the consequences are lower.
76. This all presumes that the State can do without the power provided by the power station during a major flood event. This electric power might have much greater life saving potential than the restriction of some flooding. It therefore needs to be considered with care and in association with the owners of the power station.

Item 16: A detailed description of any involvement of any DERM officer in any investigation or consideration or the preparation of any report or briefing note about the full supply level of North Pine Dam, including in relation to a temporary or permanent alteration of its full supply level since 2000.

77. I do not believe I was involved and I am not aware of any consideration of varying the full supply level of North Pine Dam, including in relation to a temporary or permanent alteration of its full supply level prior to the January 2011 flood event. I am aware that there is currently an initiative to consider a reduction in the full supply level of the North Pine Dam.

Item 17: A brief description of his role and responsibility to regulate the safety of dams on mining sites

78. I only have regulatory decision making delegations in relation to referable dams in relation to the 'referable' dam provisions of the *Water Supply (Safety and Reliability) Act 2008*. I do not have any delegated powers under the provisions of the *Environmental Protection Act 1994* (EP Act) in relation to 'regulated' dams.
79. The essential difference between 'referable dams' and 'regulated dams' is that regulated dams are those that contain hazardous waste. From a practical perspective, it relates to whether an environmental approval is required for the

dam and whether there are controls over the release of contaminants from the dam. If this is the case, then the dams effectively come under the provisions of the EP Act and are not the subject of regulation as referable dams.

80. Since October 2010 the containment systems group has been relocated into the OWSR Dam Safety group. The containment systems group provide technical advice to DERM decision makers in the regions. Technically the Director, Dam Safety is responsible for that advice.
81. This has not resulted in any significant confusion in the past and with the two groups now coming under the Office of the Water Supply Regulator umbrella there should be smoothed even further.
82. As such, I only have the power to regulate the safety of referable dams on mining sites. The referable dams connected to mines are listed in the following table. These dams are regulated in the same manner to all other referable dams.

Referable Dam No.	Name of Dam	Dam Owner	Mining Lease
174	Leichhardt River Dam	Mount Isa Mines Limited (Xstrata)	
222	Environmental Dam, Blair Athol Coal Pty Ltd	Rio Tinto	
235	Bundoora Dam	Anglo Coal (Capcoal Management) Pty Ltd	ML 1831
406	Rockland Creek Dam, Blackwater Coal Mine	South Blackwater Coal Limited (BMA Blackwater Mine)	
416	Perry River Dam	LGL Mount Rawdon Property Holdings Pty Ltd	
701	Rifle Creek Dam	Mount Isa Mines Limited (Xstrata)	
766	Cerito Creek Dam, Newlands Coal Mine	Xstrata Coal Queensland Pty Ltd	ML 4774
1822	Down Dip Dam, South Walker Coal Mine	BHP Billiton Mitsubishi Alliance	ML 4750
1952	Suhrs Creek Dam	Charters Towers Regional Council	

Item 18: A description of the actions taken or directed by him in preparation for and during the 2010/2011 wet season with respect to the safety of dams on mining sites.

83. Again I have no regulatory role over 'regulated dams' on mining sites. That role is delegated to regional DERM personnel. Members of the Containment Systems group of the Office of the Water Supply regulator provide technical advice. I believe that Mike Birchley, the Assistant Director-General, Regional Service Delivery will be addressing this issue in his statement to the Commission.

References

84. Cooper (2011), Letter to Water Grid Manager dated 12 January 2011 presenting the results of his review of the operation of Wivenhoe Dam between 12 December 2010 and 12 January 2011.

I make this solemn statement on oath conscientiously believing the same to be true, and by virtue of the provisions of the *Oaths Act 1867*.

Signed  :

Peter Hugh Allen

Taken and declared before me, at Brisbane this 12th day of September 2011


Solicitor/Barrister/Justice of the
Peace/Commissioner for Declarations

PHA 20

PHA 21

PHA 22

PHA 27

PHA 28

PHA 29

PHIA 21

Flood Operations of Wivenhoe and Somerset Dams

Notes on the Analysis of the Late December 2010 Flood Event

Introduction

This modelling has been undertaken to investigate whether the flood storage in Somerset and Wivenhoe Dams could be drained down to 75% of the current Full Supply Level (FSL) storage capacity following the 'Late December 2010' flood event.

This report looks at the effect of adopting different operational releases during the final stage of the final drainage phase of the flood storage in Wivenhoe Dam following the 'Late December 2010' flood event prior to the onset of the January 2011 flood event.

The performance of the dams depends on:

- the magnitude of the flood event coming into dams
- the timing and the magnitude of downstream inflows
- the required 'end of event' target storage levels in each reservoir

The following scenario was modelled.

- Flood operations in accordance with Revision 7 of the Flood Mitigation Manual for flood operations for Wivenhoe and Somerset Dams (Seqwater, 2010).
- Initial storage levels as they were prior to the late December 2010 flood event i.e. Wivenhoe Dam at EL 67.3 mAHD and Somerset Dam at EL 99.45 mAHD.
- Somerset Dam was assumed to be operated the same way it actually was operated during the late December flood event. This was reasonable because the flood storage in Somerset was effectively drained into Wivenhoe Dam well before the start of the January event and variations would not significantly affect the overall results.
- After the peak of the event as it passed through Wivenhoe Dam, the flood storage would be drained to return Wivenhoe Dam to EL 67.0 mAHD and Somerset Dam to EL 99.0 mAHD. This part of the drainage phase would follow the existing flood operating rules contained in Revision 7 of the FMM.
- Following the event, final drainage of Wivenhoe Dam from EL 67.0 mAHD (100%) to EL 64.0 mAHD (75%) would be undertaken using an operational release not exceeding an adopted maximum Lowood discharge criteria.

Under the current Manual the flood storage should be drained within seven days of the peak in Wivenhoe Dam. However it is recognised that, for major flood events, this period may need to be extended so as not to cause additional flooding problems during the drainage phase. Similarly, for relatively small flood events, it may be possible to reduce the drainage time to prepare the storages for the next event earlier. It is up to the Senior Flood Operations Engineer to determine how quickly the flood storage should be drained and whether/how this needs to be adjusted because of the magnitude of the event and whether more rain is forecast in the catchment.

Details of the 'Late December 2010' flood event were taken from the Seqwater flood event report for this event (Seqwater, 2011).

Details of Modelling

The model was based on an EXCEL spreadsheet which was developed following the January 2011 flood event to model the operations of Wivenhoe Dam and Somerset Dam. Macros were developed to mimic the strategies contained in the *Manual of Operational Procedures for Flood Mitigation for Wivenhoe Dam and Somerset Dam* (version 7, November 2010) (the Manual).

For the purposes of this modelling, it was adopted that the event started at midnight on the night of the 25th December 2010. There were some inflows prior to this time but these are reflected in the starting level at that time. i.e. When the FSL of Wivenhoe was EL 67.0 mAHD, the starting level for the modelling was EL 67.3 mAHD and the level in Somerset was EL 99.45 mAHD.

Inflow hydrographs were based on the modelled inflow hydrographs set out in the Seqwater Flood Event report (Seqwater, 2011).

Note that in the Figures displaying the results of the flood routing studies in this report, the Lockyer discharge hydrographs were 'brought forward' by two hours to more clearly show how the hydrographs would have combined when the flows combined with the Brisbane River flows. Similarly, the Bremer River flows were brought forward by fifteen hours to allow for the travel time from Wivenhoe Dam to where the Bremer River joins the Brisbane River.

The discharge from Wivenhoe Dam was controlled by:

- (a) Applying the operating strategies set out in the Flood Mitigation Manual
- (b) Limiting the discharge from Wivenhoe to magnitude of the maximum inflows into the storage up to that time so that releases did not aggravate downstream flooding.
- (c) Limiting the discharge from Wivenhoe to limit the maximum discharge at Lowood to 1900 m³/sec. Note that while Strategy W2 was triggered there was no need to increase the discharge beyond 1900 m³/sec to control the flood event.
- (d) Once the peak headwater level in Wivenhoe Dam had been achieved, the strategy was to continue at the maximum discharge during the drainage phase down to EL 67.0 mAHD until the flow could be reduced to a targeted maximum operational release and to open downstream crossings.
- (e) Once the Wivenhoe headwater level drops below EL 67.0 mAHD, the releases from Wivenhoe Dam during the final drainage to EL 64.0 mAHD transitioned to the maximum operational release. This analysis examined maximum operational releases of 430 m³/sec and 700 m³/sec.
- (f) File: G:\WIR\Dam Safety\QLD Floods Commission\Modelling\Effect of Late Dec flood\GateOPsv4a-Dec 2010 Case 4 67 to 64 restricted to 430.xls

Limitations on the Accuracy of this Modelling

Overall the results of these analyses should be indicative of what would have occurred during the actual event had Wivenhoe Dam been operated in the way indicated.

However, any such modelling is always an approximation of what might actually occur in real life. Usually, the more detailed the modelling, the more accurate the

results will be. These limitations limit the ability to transfer the results to actual events and the results need to be treated with care.

These limitations, which are discussed in more detail in the following paragraphs, relate to:

- (a) The accuracy of the modelling of the physical processes involved; and
- (b) The way the dams are operated during the flood

Because of these limitations, the results are more 'a relative indication' of what might occur for these events rather than a real time simulation.

Accuracy of the Modelling of Physical Processes

The model does not take into account any of the attenuation effects as the flood peaks from the dams move downstream. Instead the discharges from the Lockyer were lagged by 2 hours and the discharges from the Bremer were lagged by 15 hours to take into account the approximate travel time between Wivenhoe Dam and the locations where these tributaries enter the Brisbane River.

Because no damages were involved in this flood event, the consequences of this 'simplification' are not considered very significant.

Accuracy of Modelling of Flood operations

The modelling is in effect done in 'hindsight' with the actual flows known to a relatively high degree of accuracy. As such, it did not consider the uncertainties that Duty Flood Operations Engineers must consider when determining the magnitude of flood releases. These include:

- The degree of saturation of the Brisbane River catchments. They would have been saturated at the time and would have responded quickly to rainfall.
- The accuracy of the BoM forecast rainfalls and their intensity
- The 'representativeness' of the recorded rainfalls
- The accuracy of the hydrologic modelling converting the 'recorded' rainfall already on the ground into runoff and the discharge estimates downstream tributary inflows
- Short term local flooding effects in downstream areas which may occur after the releases have been made from the dam.
- The consequences of 'getting it wrong'. For instance, if a crossing was inundated unexpectedly and someone was injured/killed as a result, who would wear the blame?

The flood engineers consider all these things when determining the magnitude of releases. Their thinking on these issues was not known at the time this modelling was undertaken.

Because this modelling was based on an historical flood event, the magnitude and the timing of the flood hydrographs were 'known'. This meant that the dams could be operated 'aggressively' in this simulation without fear of 'getting it wrong' and right up to the limits specified in the Manual.

Thus some conservatism would have been appropriate if, for instance, a maximum release of 430 m³/sec was targeted to keep Burton's Bridge trafficable. Because of the potential consequences of unforecast rainfall, the Duty Engineer might have considered it judicious to limit the discharge to about 350 m³/sec to provide a margin for 'error'.


Maximum Operational Release of 430 m³/sec

The results of this analysis are summarised in the following Figure. They indicate:

1. If the maximum operational release is 430 m³/sec, it would not have been possible to drain the flood storage before the onset of the January 2011 flood event and the mobilisation of the Flood Operations Centre at 9:00 am on the 6th January.
2. This would have made Burton's Bridge trafficable after about 5 days during the late December flood event. This is important because Burton's Bridge is the sole point of access for people living on the left bank of the Brisbane River at that point.
3. At the time of the mobilisation of the Flood operations Centre, Wivenhoe would have been at about 86% of the Full supply Level (FSL) storage capacity and the benefits of reducing the FSL to 75% capacity would have been only partly achieved.
4. It would also have taken about 8 days to drain to that point – well beyond the preferred 7 days specified in Revision 7 of the FMM.
5. It is difficult to see how the Flood Operations Engineers would have foreseen how such a big flood event as the January 2011 event was coming at that time so that discharges could have been increased ahead of this event.

Wivenhoe Dam: Late December lead into January 2011 Flood Event


Starting with FSL at EL 67.0 mAHd, returning to EL 64.0 mAHd with a maximum discharge of 430 m³/sec



Maximum Operational Release of 700 m³/sec

Given the benefit of hind sight, an operational release of about 700 m³/sec is required to reduce the level in Wivenhoe down to EL 64.0 mAHD prior to the January 2011 flood. This is illustrated in the following Figure.

One important consequence of this scenario is that access across Burton's Bridge would have been unavailable for about 23 days during the late December flood event until it would have reopened about the 19th January 2011.



References

- Seqwater, 2010 "Manual of Operational Procedures for Flood Mitigation for Wivenhoe Dam and Somerset Dam", version 7, November.
- Seqwater, 2011 "October - December 2010, Flood Events, Report on the Operation of Somerset Dam and Wivenhoe Dam", May

Peter Allen
23rd August 2011
RPEQ 2979.
Project Director, Dam Safety
Office of Water Supply Regulator
Department of Environment and Resource Management

INCIDENT ALERT ENRR DIVISION

TYPE OF ALERT: Dam Safety Incident
INCIDENT NAME: Plunge Pool Erosion: Wivenhoe Dam
ALERT DATE: 24 January 2011
ALERT VERSION: Update
ECOTRACK & FILE REF: DAM/130/000(0377)
RESPONSIBLE MINISTER
Stephen Robertson MP, Minister for Natural Resources, Mines and Energy and Minister for Trade

CONTACT OFFICER: Peter Allen

NAME OF ALLEGED SOURCE:

- John Tibaldi, Seqwater

DATE AND TIME OF INCIDENT:

- 05:30am 19 January 2011

INCIDENT NOTIFIED BY: *(entity and person)*

- John Tibaldi, Seqwater

DATE, TIME, METHOD OF NOTIFICATION:

- Approximately 5.30 am, 19 January 2011, by phone to Peter Allen (Director, Dam Safety)

LOCATION OF INCIDENT:

- Wivenhoe Dam

SUMMARY OF INCIDENT AS NOTIFIED:

- The flood waters released by the Wivenhoe dam spillway gates pass through a plunge pool energy dissipater and along a rock chute to return to the Brisbane River.
- After a major flood event such as has been experienced, some erosion around the edges of the plunge pool is likely. This has apparently occurred
- It is a reportable dam safety incident (It does not relate to the Flood Mitigation Manual)

POTENTIAL IMPACTS:

- If the erosion is very severe, then it could ultimately compromise the safety of the dam. However, Seqwater staff have advised that the erosion does not look serious, and will not affect dam operations—including operation of the flood gates

RELEVANCE TO NEIGHBOURING LANDHOLDERS:

- There is no apparent safety risk

ACTIONS TAKEN BY COMPANY OR SOURCE OF THE INCIDENT:

- Seqwater undertook a preliminary inspection on the morning of the incident. Russ McConnell of OWSR Dam Safety also inspected the site for that inspection. His report is available on request.

- SunWater has undertaken a bathymetric survey of plunge pool and spillway chute and the results of this survey should be available soon. However, preliminary reports indicate that the damage is minor in the plunge pool and non threatening in the spillway chute.

DERM's ASSESSMENT AND PLANNED ACTIONS:

- Based on Seqwater's advice, there is no dam safety risk, and there are no impediments to the flood gates' operations.
- A senior DERM dam safety engineer has been dispatched to the site by road. A copy of his report is available if needed.

NEXT UPDATE EXPECTED : When Seqwater report becomes available.

COMMUNICATION:

- No other parties have been notified
- If media statements are required, then these would normally be progressed through the dam owner i.e. Seqwater.

MAP OR PLAN OF SITE:





WIVENHOE DAM



Post January 2011 Flood Event Embankment Analysis

June 2011

Revision		Draft for Review
Report Prepared by	Michael Peel / Barton Maher	
Reviewed and Certified	Barton Maher (RPEQ 6833)	
Approved for Issue	Jim Pruss (EGM Water Delivery)	

TABLE OF CONTENTS

1	INTRODUCTION	1
2	EXECUTIVE SUMMARY	2
3	DAM DESCRIPTION	3
4	DAM INFORMATION	5
5	JANUARY 2011 FLOOD.....	7
5.1	Wivenhoe Flood Mitigation and Dam Operations	7
5.2	Inspections of the Damage	9
5.2.1	DERM Inspection Report Summary.....	11
5.3	Description of the Damage	12
5.4	Survey Results	15
6	SPILLWAY DESIGN	17
6.1	General.....	17
6.2	Hydraulic Modelling	17
7	INSTRUMENTATION	22
8	DAM EMBANKMENT DEFORMATION	24
8.1	Pore Pressure (Hydraulic Piezometers)	24
8.2	Pore Pressure (Total Pressure Cells)	30
8.3	Deformation Monitoring.....	30
8.3.1	Dam Embankment Deformation	30
i).	Embankment Settlement	32
ii).	Embankment Displacement.....	33
8.3.2	Fuse Plug Deformation.....	35
i).	Fuse Plug Settlement	35
ii).	Fuse Plug Displacement	36
8.4	Structural Movement (Inclinometers)	37

8.5	Seepage.....	37
8.6	Post Tensioning.....	37
9	CONCLUSIONS	38
10	RECOMMENDATIONS	39
11	REFERENCES	41
APPENDIX A	DRAWINGS.....	42
APPENDIX B	JANUARY 2011 SPILLWAY SURVEY.....	55
APPENDIX C	INSTRUMENTATION DATA.....	64

DRAFT

1 INTRODUCTION

The Queensland Bulk Water Supply Authority trading as Seqwater took over ownership of Wivenhoe Dam from the South East Queensland Water Corporation Pty Ltd on 1 July 2008. In accordance with the Dam Safety Conditions issued by the Dam Safety Regulator for Wivenhoe Dam a comprehensive surveillance report was prepared and submitted to the DERM Dam Safety Regulator in September 2010.

In January 2011, Wivenhoe Dam experienced the flood of record post construction. During this flood event, the storage level reached approximately EL75, or more than 4m higher than the previous flood of record in 1999. This represented a first fill for the upper part of the two main dam embankments, two saddle dam embankments, and the fuse plug embankments. The fuse plug embankments were installed in the auxiliary spillway during the flood security upgrade of the dam in 2004 / 2005.

During the January 2011 flood, the peak outflow from the dam was approximately 7,500m³/s. This discharge resulted in significant erosion of the plunge pool floor downstream of the primary gated spillway and significant damage to the sandstone walls and recreation facilities in the spillway channel. Given the magnitude of the flood event and the subsequent damage, this document has been prepared as a special report to:

1. Detail the inspections undertaken
2. Assess the performance of the dam, and
3. Advise of the proposed actions to remediate the damage to the dam.

2 EXECUTIVE SUMMARY

The September 2010 comprehensive surveillance report found that:

"Wivenhoe Dam is generally in very good condition. The recent comprehensive design reviews undertaken by the Wivenhoe Alliance and GHD in 2003 and 2009 respectively conclude that the design of the dam is in accordance with modern day standards and that there are no outstanding design issues that require investigation at the present time.

Data obtained from the dam safety instrumentation at the dam shows that the structural performance of the dam is satisfactory and in accordance with design expectations. No issues were identified as a result of the comprehensive review of the instrumentation data. The physical infrastructure at the dam is generally maintained in good condition and all other major dam components are performing satisfactorily.

As part of the Comprehensive Inspection, Queensland Hydraulics completed a comprehensive investigation and review of the hydraulics systems that power the operation of the radial gates and crane. The subsequent report (see Appendix C) concluded that these systems are in good condition and should have a minimum of 10 additional years of working life before requiring major refurbishment. These systems will be reviewed again as part of the next comprehensive inspection in 2015."

During the January 2011 flood event, the dam operators noted an increase in tail water level and turbulence in the spillway channel as the discharges were decreased after the flood peak. The increase in tail water was caused by a large amount of rock that had been deposited in the spillway chute. This was reported to Seqwater Dam Safety Staff and an inspection undertaken immediately after the closure of the spillway gates at the end of the flood event. The DERM Dam Safety Group was notified of the spillway scour and attended the site inspection.

3 DAM DESCRIPTION

Wivenhoe Dam was designed by the Queensland Water Resources Commission. Construction began in 1977 and when completed in 1984, Wivenhoe Dam was a 56 metre high, zoned earth and rock embankment separated into two parts by a concrete gravity spillway. The spillway is controlled by 5 radial gates, each 12.0 metres wide by 16.0 metres high. Two saddle dam embankments are located on the left side of the reservoir. The Brisbane Valley Highway was relocated to pass over and along the crest of the dam embankment.

The Left Bank embankment is approximately 1.1 kilometres long and is constructed with a sloping upstream core. The core is protected by filters (located both upstream and downstream) and supported by a downstream shell of miscellaneous fill. Batter slopes are 3 horizontal to 1 vertical on the upstream face and 2 horizontal to 1 vertical on the downstream face. Riprap is also in place on the upstream and downstream shoulders of the embankment.

The Right Bank embankment is 1.2 kilometres long and 56 metres high with a central clay core. The embankment contains both upstream and downstream filters supported by outer shells of compacted sandstone with river run gravel in the upper portion. The shoulder slopes are 2 horizontal to 1 vertical with a local steepening in the upper portion to 1.5 horizontal to 1 vertical. Riprap is in place on both the upstream and downstream shoulders of the embankment.

Two saddle dams close off low points located along the left abutment of the dam. Saddle Dam 1 is a homogeneous embankment constructed from miscellaneous fill. Saddle Dam 2 is the higher of the two embankments and is constructed with a central clay core and random fill shoulders. Rip Rap is provided for both embankment on the upstream face for wave protection and the downstream slope is topsoiled and grassed. The Saddle Dams have a crest level at EL 80 and have a maximum height of 10 m. The Saddle Dams only retain water during flood operation.

The dam spillway capacity was upgraded in 2005 by the Wivenhoe Alliance. The works associated with this upgrade are summarised as follows:

- Construction of a 164 metre wide secondary spillway through the right abutment of the existing dam, in an excavated chute that included concrete works for a 3 metre ogee crest, apron slabs, chute lining and the divider walls to enable construction of three eroding earth fill fuse plug embankments;
- Upgrading of the wave wall on the two main embankments to handle the new Maximum Flood Level (MFL) of EL 80.0;
- Strengthening of the primary spillway with post-tensioned anchors to cater for the increased loading due to the raised flood level.
- Provision of a steel deflection baffle upstream of the radial gates to ensure the gates clear the flow profile for the raised MFL.

These works raised the dam crest flood from a 1 in 22,000 AEP event to 1 in 100,000 AEP flood event. The initial trigger level for the first fuse plug embankment is at EL 75.7m (approximately the 1 in 6,000 AEP flood event).

The dam has four main functions by providing:

- A 1.165 GL storage at full supply level (FSL EL 67.0) providing an urban water supply for Brisbane and surrounding areas;
- Flood mitigation in the Brisbane River by providing a dedicated flood storage volume of 1.45 GL up to EL77 (the MFL was increased to EL80m as part of the Wivenhoe Alliance Upgrade works in 2005 changing the flood storage volume to 2.0GL at EL80m);
- A source of supply for the Split Yard Pumped Hydro-Electric power station which has a 500 MW generating capacity;
- A recreation area.

The dam has an EXTREME hazard classification under ANCOLD guidelines because of the significant development downstream in the Brisbane and Ipswich metropolitan areas, with the population at risk (PAR) numbering in the hundreds of thousands.

4 DAM INFORMATION

 seqwater WATER FOR LIFE	WIVENHOE DAM
Population at Risk	Sunny Day Failure: 244,000 Flood: >1,000 (not fully assessed)
Failure Impact Rating	2
Hazard Category	Extreme
Dam Owner	Seqwater
Name of Reservoir	Lake Wivenhoe
Year Complete	1984
Location	Approximately 5km upstream of Fernvale
Water Course	Brisbane River
Purpose	Town water and flood mitigation
Type of Construction	Zoned earth and rockfill embankment
Outlet Works	Radial gated spillway with supplementary fuse plug spillway
Catchment Area	7,020km ²
FSL	67m AHD
Full Supply Capacity	1,165,238 ML
Surface Area at FSL	10,750ha
Main Dam Crest	79m AHD
Main Dam Embankment Length	2,300m
Maximum Height of Main Dam Embankment	56m
Width at Top of Main Dam Embankment	10.0m
Spillway Crest	57.0m AHD
Spillway Length	60m
Gates	5 radial gates 12m wide x 16.0 m high
Top of Closed Gate	EL 73.0m
Saddle Dam Crest	80.0m AHD
Saddle Dam Length	3 x total length of 518
Maximum Height of Saddle Dam Embankment	10.0m
Peak Water Level as a Result of PMF	Dam Overtopped
Spillway Capacity (including Fuse Plugs)	28,100m ³ /s (EL 79.0m)
Maximum Discharge as a Result of PMF	37,400m ³ /s
AEP of Spillway Capacity (including Fuse Plugs)	1 in 100,000 (EL 79.0m)
Regulator valves	1 x 1.5m cone dispersion valve
Mean annual pan evaporation	1,600mm (BOM estimate)
Mean annual rainfall	986mm
Hydroelectric Facilities	4.3 mw mini-hydro
Notable events (Post Dam)	1986, 1989 (x 2), 1999, 2011
Maximum Historic Storage Level	74.8 m AHD January 2011

Comment	Besides being a major source of urban water supply, Wivenhoe Dam provides a significant flood mitigation capacity to protect the urban areas downstream of the dam. During periods of heavy rainfall, flood water is temporarily stored in Wivenhoe Dam and released at a controlled rate to minimise the impact of downstream flooding. The dam was built in conjunction with Splityard Creek Dam and water from Wivenhoe is pumped into Splityard Creek Dam where it is used to generate electricity during periods of high demand.
----------------	---

5 JANUARY 2011 FLOOD

Flood data and a description of dam operations during the January 2011 event are contained in Seqwater's report entitled 'January 2011 Flood Event – Report on the operation of Somerset Dam and Wivenhoe Dam' dated 2 March 2011 which has been submitted to DERM. Please refer to this report for any additional information or clarification regarding the January 2011 Flood Event. Key points for the January 2011 flooding include:

1. The flood can be categorised as a large (Annual Exceedance Probability [AEP] of 1 in 100) to rare (AEP of 1 in 2,000 years) event as defined by *Australian Rainfall and Runoff (Book 6)* (AR&R).
2. The volume of total inflow into Wivenhoe Dam during the Event was 2,650,000ML.
3. This flood event had a peak inflow of approximately 10,600m³/s.

5.1 Wivenhoe Flood Mitigation and Dam Operations

For the January 2011 floods, there were three distinct events within the flood. Reference Figure 1 and Figure 2. These were:

1. Flood event that occurred from 5 to 7 January 2011:
 - Peak inflow of approximately 2,000m³/s
 - Peak outflow was approximately 475m³/s
2. The first of the two major flood events then began to enter Wivenhoe Dam at around 1 am on 8 January 2011 with the peak occurring at 10 pm on 8 January 2011.
 - Peak inflow of approximately 10,600m³/s
 - Peak outflow of approximately 4,000m³/s.
3. The second of the two major flood events then began to enter Wivenhoe Dam at around 8 pm on 9 January 2011 with the peak occurring at 10 am on 10 January 2011.
 - Peak inflow of approximately 9,800 m³/s
 - Peak outflow was approximately 7,500 m³/s

Following the peak discharges from the dam, the dam operators reported to the flood operations centre an increase in the observed tail water levels and the turbulent flow as discharges passed over the rock pile at the end of the chute.




Figure 1 - Inflow and Outflow Hydrographs at Wivenhoe Dam for January 2011 Floods




Figure 2- Wivenhoe Lake Level during January 2011 Floods

5.2 Inspections of the Damage

After the peak outflow of the flood event, operators at the dam noted that the tail water level had increased and was artificially high following the closing of the gates. There was also significant turbulence in the middle of the spillway chute.

Once flows from the spillway were reduced, large rocks were noted at the end of the plunge pool and reported to the flood control centre. However, it was not until the gate closing sequence was initiated at the end of the flood event that the scale of the erosion was apparent to the operators at the dam. The Seqwater Principal Engineer Dam Safety (John Tibaldi) was notified of the scour and an inspection was arranged as soon as it was possible to shut off the spillway gates. The Office of the Dam Safety Regulator at DERM was also notified of the scour and invited to attend the inspection of the spillway upon closing the spillway gates.

On the morning of the 19th of January, the storage level was approaching EL 67m and the spillway gates were able to be closed, enabling an inspection of the Wivenhoe spillway channel. The inspection team comprised of Mr Barton Maher (Seqwater Principal Dams & Weirs Planning), Mr John Tibaldi (Seqwater Principal Engineer Dam Safety), Mr Jim Pruss (Seqwater Executive General Manager Water Delivery), Rob Drury (Seqwater Manager Dam Safety and Source Operations) and Russ McConnell from the Office of the Dam Safety Regulator (DERM).

- January 19th @ 6:00 am
 - The inspection commenced on site. The scour of the spillway was viewed from the crest, adjacent recreational areas, and wherever safe access could be achieved to observe/assess the large pile of rocks. The consensus from the inspection team at this time was that the rock had most likely been removed from the floor of the plunge pool based on the observations of the side walls of the spillway chute. Safe access to the rocks within the spillway outlet channel was not possible at that time due to the releases from the radial gates. Therefore the inspection team undertook an inspection of the dam crest and the auxiliary spillway.
 - Further inspection of Wivenhoe Dam along the main embankment crests revealed no signs of any movement, cracking, or misalignment along the road pavement and wave wall of the main embankment and the left hand side embankment.
 - Longitudinal cracks were identified along the upstream side of the crest of the fuse plug embankments. These cracks were excavated but only persisted through the road base capping on the clay core. These appeared to be due to small movements at the joint of the rockfill and the clay core and were only 100mm deep at the most. It is considered that they were most likely due to settlement of the upstream rip rap following the drawdown of the storage.
 - The upstream training walls in the auxiliary spillway chute had evidence of water leaking through the horizontal construction joints in the concrete facing. This was predominantly where the concrete facing was decreased in thickness to 150mm from the maximum section of 300mm. There was water seeping from various drains. There was no visible evidence of misalignment or movement for the chute walls. Aside from the small longitudinal cracks in the road base capping the fuse plug embankments appeared to be in good condition with no sign of movement, bulging of the toe or misalignment.

- January 19th @ 11:00 am

- The spillway gates were closed, allowing a more detailed inspection of the erosion in the primary spillway chute. It was noted that the mound of boulders (in excess of 1000 tons) developed approximately 150 metres downstream of the dam spillway. It was agreed that these boulders were most likely excavated from the floor and the side benches of the spillway outlet channel by the force of the water being released during the peak outflow of the flood event. This opinion was derived from the observation of the side walls of the spillway channel where the vertical sides of the excavated rock were still intact. The symmetrical operation of the spillway gates appeared to have successfully prevented damage to the side wall of the spillway outlet channel immediately below the flip bucket. Preliminary comments from the inspection team in relation to this mound of boulders were:

- The development of the mound of boulders is consistent with design expectations based on the physical modelling of the dam and was expected to occur during an extreme release of water from the dam such as the one recently experienced.
- A diving inspection should be undertaken as soon as possible to determine if there had been any head cutting of the plunge pool rock that could undermine the concrete apron protecting the spillway structure.
- There was no immediate threat to the safety of the dam as the concrete apron slab downstream of the flip bucket was intact and showed no evidence of any damage.
- Remedial works would be required if there was any evidence of the erosion undercutting the concrete apron downstream of the flip bucket.

Contact was made with a diving company that had been previously utilised by Seqwater. Arrangements were made to undertake a diving inspection of the plunge pool the following morning.

SunWater surveyor, Bill Hewitt was on site on the 19th of January undertaking the annual deformation survey for the dam. SunWater hydro graphic and GPS equipment was available on site which also enabled a hydrographical survey of the plunge pool to be undertaken in conjunction with the diving inspection. Results are detailed in section 5.4 of this report.

- January 20th

- The diving inspection was undertaken and showed that no significant under-cutting of the spillway structure had occurred as a result of the development of the boulder mound. There was evidence of some very localised undercutting in two locations, potentially indicating the presence of weaker seams in the rock mass. The extent of this undercutting was very limited. It should be noted that even if extensive undercutting had occurred, the spillway post-tensioning that was undertaken in 2005 would have ensured the safety of the dam. The observations made during the inspection were:

- At Mono S2, approximately one third of the way across the apron slab from the left hand joint there was undercutting of the concrete apron. The undercutting occurred over a length of 1.5m horizontally and extended 0.5m underneath the concrete apron. The diver was able to follow the vertical face of the concrete apron down to the rock. A rock ledge extended out from the concrete approximately 1m into the plunge pool. This rock was

approximately 1 – 1.5m deep and formed a roof over the undercutting. The undercutting beneath this rock roof extended back underneath the concrete apron. Dimensions for the erosion hole were 1.5m horizontally, 1m, vertically and 1.5m from the front edge to the back of the hole.

- At Mono S5, there was evidence of a very small undercut of the concrete apron. This was approximately 0.4m under the concrete and extended for only 0.5m horizontally with a depth of 0.2m.
- Preliminary results were obtained for the hydro graphic survey. These results showed that the majority of the erosion had occurred at the downstream end of the excavated plunge pool and there was no evidence that the sides of the spillway channel had been eroded significantly.

Additional conclusions from the inspection team included:

- The boulder mound could be advantageous in for large flood events in the short term because it causes elevated tail water levels that aid energy dissipation and scouring depth. However the down side is that the elevated water levels may adversely impact the cone valve operations during routine, low volume water releases downstream (releases are still possible, but the elevated tail water will cause minor but repairable damage to the valve over time; a spare valve is also available at the dam). The boulder mound will however have absolutely no impact on low volume water releases from either the radial gates or mini-hydro. Note: it will impact on the head and thus the generation capacity of the hydro releases.
- The future of the boulder mound will be considered over coming weeks. Options to be examined in detail include leaving the mound as is, removing small sections, or removing it entirely. In the very short term, it will be left undisturbed because it causes no significant operational issues.

5.2.1 DERM Inspection Report Summary

Russ McConnell, Manager Containment System, OWSR, DERM inspected and issued report s.37 Consultation, RTI Act 2009, DERM Application No. 10-207. The report outlines the background and observations of Wivenhoe Dam from his site visit on 19th January 2011. Detailed out are outstanding issues regarding his investigation and expected action steps for Seqwater.

Post Inspection Issues:

1. "By lateral expansion of the plunge pool cavity at depth to beneath the walls of the spillway, thus decreasing their stability; or"
2. "By head ward erosion of the plunge pool cavity upstream towards or to beneath the apron and flip of the spillway structure."

Expected Actions Steps:

1. "Undertake a bathymetric survey of the plunge pool floor by a depth gauge attached to a boat starting on 20th January 2011."
2. "Investigate lateral expansion extent (if any) by professional divers in the spillway walls and the spillway toe starting on 20th January 2011"

The bathymetric survey and diving inspection undertaken by Seqwater have confirmed that:

1. Lateral expansion of the plunge pool has not occurred. Most rock has been removed at the downstream side of the excavated plunge pool.
2. Very little head ward erosion has occurred with no significant undercutting of the concrete apron slab protecting the flip bucket.

5.3 Description of the Damage

During the January 2011 flood event, the flow rate released from Wivenhoe Dam Spillway peaked at approximately 7,500 m³/s. The area directly downstream of the Wivenhoe Dam Spillway experienced significant erosion and scour damage to the plunge pool, outlet discharge channel, lower dam access roads, and spillway lookout recreational area. Initial estimates of the volume of the rock eroded from the plunge pool of over 25,000 m³ of material. In particular, multiple boulders in excess of 700 tons have been displaced and deposited downstream. The two lower dam access roads, used for equipment entry to the low level gates and hydropower station, were washed out.

Flows spilling out of the spillway channel at the downstream end of the spillway chute resulted in significant erosion. Material was removed down to moderately weathered rock. Significant damage was found on the left hand side of the channel downstream of the lookout where mudstone joints were washed out and significant amounts of rock removed.

The spillway lookout recreational area had erosion cut down to the underlying rock material, leaving behind near vertical soil slopes up to 3 metres high, as well as damage to the bitumen roads and parking lots. The following photos are representative before and after shots of the January 2011 flood.



Photo 1- Wivenhoe Outlet Channel and Spillway Prior to January 2011 Flood



Photo 2- Wivenhoe Outlet Channel and Spillway Post January 2011 Flood



Photo 3- Wivenhoe Outlet Channel and Spillway Prior to January 2011 Flood



Photo 4- Wivenhoe Outlet Channel and Spillway Post January 2011 Flood



Photo 5- Wivenhoe Outlet Channel and Spillway Post January 2011 Flood



Photo 6- Wivenhoe Outlet Channel and Spillway Post January 2011 Flood

5.4 Survey Results

The hydrographical survey of the spillway and plunge pool was conducted on the 20th of January immediately after the flood releases could be stopped. The surveyor utilized a boat, GPS, and depth sounding equipment to obtain the data on the spillway erosion. Figure 3 below shows a plan view of the locations of cross-sections. Figure 4 is the cross-section profile at location A-A. Additional information is available in the Appendix B.

It can be seen from cross section A-A in Figure 4 (left to right represents upstream to downstream) that the majority of material removed from the base of the plunge pool was located at the downstream side of the excavation. The plunge pool depth was decreased to a depth of EL14m and up to 10m of rock was removed from areas of the spillway structure. However, it should be noted that there was minimal head cutting of the upstream side of the plunge pool.




Figure 3 - Survey of Wivenhoe Outlet Channel and Spillway Post January 2011 Flood




Figure 4 - Survey of Wivenhoe Outlet Channel and Spillway Pre and Post January 2011 Flood

6 SPILLWAY DESIGN

6.1 General

According to the Wivenhoe Dam Design Report (DPI Water Commercial, 1995), the excavated channel for the spillway has a total length of approximately 1,100m. It has a low level channel to serve the outlet works, which was also used for diversion during construction, and a higher approach channel serving the other four overflow monoliths. Downstream of the spillway flip bucket, the discharge channel was excavated an additional 11 m where the discharge jet impinges, to form a plunge pool, which is designed to dissipate the energy and control scouring.

Bays on the spillway overflow crest are five in number, each 12 m wide. A high level spillway flip bucket, of uniform radius directs an overflow jet well away from the crest structure. Steel radial gates of 90 t mass are mounted off piers supported on the crest, lifting winches being located behind each gate leaf. Each pier is a constant 3.5 m width for 12 m from its nose and then tapers to 2 m at its downstream end. At the base of each pier an extension is provided to reduce unsteady flow conditions in the spillway flip bucket.

Twin bridges cross the spillway. One carries the highway and is sported on cantilevers off the piers. A second bridge supports a 79 t gantry crane provided to install the bulkhead gate during maintenance of any radial gate.

An intake structure for the outlet works is slotted into the left bank spillway retaining wall just upstream of the spillway crest. Outlet pipes of 1,900 mm and 3,600 mm diameter, one above the other, connect the intake to the discharge valves adjacent to the spillway flip bucket. The 3,600 mm diameter pipe was providing as a possible power station penstock.

The dam site lies on the Helidon Sandstone, formerly known as the Wivenhoe Sandstone. This rock is a massive, thickly bedded, fine to coarse grained argillaceous sandstone of varying hardness, commonly showing current bedding which is approximately horizontal. Shale, claystone and coal are also present in occasional seams and lenses.

6.2 Hydraulic Modelling

Most of the hydraulic data for the spillway design was obtained by testing of two physical hydraulic models. A 'pilot' model was used to determine the feasibility of the flip bucket spillway and to assess overall hydraulic behaviour of the spillway, the approach flow conditions and discharge back to the river. The second 'main spillway' model, was tested to determine the spillway structure geometry, hydraulic loading data, gate discharge ratings, proposed sequencing of gate openings for flood discharge, and dissipation performance in the plunge pool.

During the design of the spillway using the physical model, it was deemed virtually impossible to reproduce in the model the scour of the rock material in the discharge channel. It was determined that if the discharge channel had a non-erodible bed at El. 28.0 supercritical flow was possible with a hydraulic jump being formed at the downstream end of the channel. This was considered undesirable. Massive scour could develop in the less resistant rock at the downstream end of the discharge channel and result in uncontrolled back erosion, progressing upstream from the end of the channel and potentially putting the dam at risk. For this reason, a pre-excavated scour hole was experimented with to ensure that energy dissipation occurred in the region where the jet impacted the bed of the discharge channel and thus controlled the location of the major scour expected from the design flows. This concept was further tested in the main spillway model utilizing a gate controlled discharge of 5,000 m³/s and an uncontrolled discharge of 11,700 m³/s. The design

discharge of 3,000 m³/s was estimated to be a zero damage discharge and subsequently not tested in the physical model.

The pre-excavated plunge pool was considered necessary to initiate the scour hole downstream of the flip bucket in a controlled manner. The basic consideration in the development of the pre-excavated plunge pool shape was that the large scale turbulence should be concentrated away from the unprotected sidewalls of the spillway discharge channel. The final plunge pool configuration of the excavated benches protected the sidewalls from undermining, and sloping the downstream bench faces reduced the possibility of deflecting the jet laterally.

It was therefore anticipated, at the time of design, that the plunge pool would undergo further scour when subjected to flows above 5,000 m³/s. The extent of the scour was not able to be determined due to the difficulty of modelling the scouring process. However, using a moveable bed in the physical model resulted in scouring of the plunge pool to a level of EL -20m.

Below are a series of photographs taken during the construction of the Wivenhoe Outlet and Spillway Plunge Pool.



Photo 7- Wivenhoe Outlet and Spillway Plunge Pool Construction



Photo 8- Wivenhoe Outlet and Spillway Plunge Pool Construction



Photo 9- Wivenhoe Outlet and Spillway Plunge Pool Construction




Photo 10- Wivenhoe Outlet and Spillway Plunge Pool Construction



Photo 11- Wivenhoe Outlet and Spillway Plunge Pool Construction




Photo 12- Wivenhoe Outlet and Spillway Plunge Pool Construction




Photo 13- Wivenhoe Outlet and Spillway Plunge Pool Construction

7 INSTRUMENTATION

A summary of the dam safety monitoring instrumentation at Wivenhoe Dam is contained in the following table.

WIVENHOE DAM – DAM SAFETY INSTRUMENTATION	
TYPE	DESCRIPTION
Pore Pressure (Hydraulic Piezometers)	There are 60 hydraulic piezometers installed at the dam to monitor pore pressure. There are 24 piezometers at Ch 1600 and 22 piezometers at Ch 1800, in the right bank earth embankment. There are 14 piezometers at Ch 1200, in the concrete spillway section. There are 5 piezometers at Ch 1960, in the core of the diversion channel section of the right bank embankment. These instruments are read monthly.
Pore Pressure (Total Pressure Cells)	There are 25 total pressure cells installed at the dam. There are 11 total pressure cells at Ch 1600 and 11 total pressure cells at Ch 1800, in the right bank earth embankment. There are 3 total pressure cells at Ch 1960, in the core of the diversion channel section of the main embankment. The reading of these instruments was abandoned in the 1990s (see discussion below).
Deformation Monitoring- Dam Embankment	There are 60 movement monitoring points installed at the dam to measure embankment movement. There are 48 movement monitoring points installed in the right bank earth embankment and 12 movement monitoring points installed in the right abutment spillway. A deformation survey is undertaken annually.
Deformation Monitoring- Fuse Plug	There are 12 movement monitoring points installed at the fuse plug and the adjacent areas to measure the movement of this structure. A deformation survey is undertaken annually.
Structural Movement	There are 10 inclinometers installed at the dam to measure structural movement. There are 4 inclinometers installed in the right bank earth embankment and 6 inclinometers installed in the right abutment spillway. These instruments are read monthly.
Seepage	V-notch weirs are located in lower gallery of spillway and in the diversion channel section of the right bank embankment to measure seepage. V-notch weirs are also used to measure seepage flows from the left and right bank embankment drainage systems. These instruments are generally read on a daily basis.

Rainfall and Storage Level	Alert canisters transmit this data continuously in real time. All data is stored by Seqwater within a database.
----------------------------	---

Monitoring Frequencies

Monitoring frequencies are undertaken in accordance with the following table that meets ANCOLD Guidelines.

WIVENHOE DAM – DAM SAFETY INSTRUMENTATION	
TYPE	MONITORING FREQUENCY
Rainfall and Storage Level	Monitored daily through ALERT
Seepage	Daily
Pore Pressure	Monthly
Structural Movement	Monthly
Deformation Monitoring	Yearly

The Hazard Category of Wivenhoe Dam is Extreme. Instrumentation monitoring is undertaken in accordance with ANCOLD Guidelines.

8 DAM EMBANKMENT DEFORMATION

Dam embankment investigations identify three key phases during a dam timeline for deformation analysis: during the construction, at the first filling, and long term performance. An additional cause of deformation, particularly after the first fill, is an abnormal change in the normal forces. These forces are identified but not limited to earthquakes and unplanned reservoir fluctuations. In the case of Wivenhoe Dam, it has experienced a drought and flood of record all within the previous 3.5 years. Water level fluctuations increased almost 25 m during this time. The reservoir draw down was gradual in nature, but the January 2011 flood event alone increased the water level 7.5 m from FSL in a week with ongoing spillway releases of up to 7,500 m³/s. Ideally, the best way to assess the performance of Wivenhoe Dam is a comparative analysis to similar constructed embankment structures utilizing applicable instrumentation data and determines what the typical deformation values are.

8.1 Pore Pressure (Hydraulic Piezometers)

The January 2011 flood inflicted damage to the piezometer data recording housing unit and the data was not retrievable until May 2011. Unrecoverable data includes information dated January 13th and February 28th. Detailed graphs showing the behaviour of individual piezometers over time are contained in Appendix C.

PIEZOMETERS	DESCRIPTION	COMMENTS	CURRENT TRIGGER
WVH01 WVH02 WVH03	These three piezometers are located within the sandstone foundation at EL 15 metres under the embankment core at Ch 1600. WVH01 is 11 metres upstream of the embankment centreline, WVH02 is on the embankment centreline and WVH03 is 11 metres downstream of the embankment centreline. The grout curtain is located midway between WVH01 and WVH02.	The pressure drop across the grout curtain remains in the order of five metres, indicating some leakage across the curtain. This is in line with historical performance. Due to damages to the piezometer housing, it is possible that WVH02 readings exceed the trigger level of 42 metres during the January 2011 flood event. After the flood, the piezometers levels have receded, as expected, and fall in line with historical trending.	Any reduction in the pressure differential between WVH01 and WVH02 to a value equal to or below 4.5 metres should trigger additional monitoring and investigation. Any increase in the pressure reading for WVH02 in excess of EL 42 metres should trigger additional monitoring and investigation.
WVH04 WVH05 WVH06 WVH07 WVH08	These six piezometers are located at EL 25 metres within the embankment core and downstream filter at Ch 1600. The piezometers are fairly evenly spaced. WVH04 and WVH05 are within the core, 11 metres and 5 metres	The pressure readings from these piezometers are consistent with historical performance dating back to the first filling of the dam in 1988. There is nothing to indicate that any of the piezometers have approached the trigger	Any increase in the pressure reading for WVH05 in excess of EL 55 metres should trigger additional monitoring and investigation. Any increase in the pressure reading for WVH08 in excess of EL 35

WVH09	respectively, upstream of the embankment centreline. WVH06 is within the core on the embankment centreline. WVH07 and WVH08 are within the core, 5 metres and 9.5 metres respectively downstream of the embankment centreline. WVH09 is within the downstream filter, 13.6 metres downstream of the embankment centreline.	levels for this section.	metres should trigger additional monitoring and investigation.
WVH10 WVH11 WVH12 WVH13	These four piezometers are located at EL 35 metres within the embankment core at Ch 1600. The piezometers are fairly evenly spaced. WVH10 and WVH11 are 8 metres and 3 metres respectively, upstream of the embankment centreline. WVH12 and WVH13 are 3 metres and 8 metres respectively downstream of the embankment centreline.	The pressure readings from these piezometers are consistent with historical performance dating back to the first filling of the dam in 1988. Due to damages to the piezometer housing, it is possible that the readings exceeded the trigger levels during the January 2011 flood event. After the flood, the piezometers levels have receded, as expected, and fall in line with historical trending	Any increase in the pressure reading for WHV11 in excess of EL 47 metres should trigger additional monitoring and investigation. Any increase in the pressure reading for WHV13 in excess of EL 37 metres should trigger additional monitoring and investigation.
WVH14 WVH15 WVH16 WVH17	These four piezometers are located at EL 45 metres within the embankment core at Ch 1600. The piezometers are fairly evenly spaced. WVH14 and WVH15 are 7.5 metres and 2.5 metres respectively, upstream of the embankment centreline. WVH16 and WVH17 are 2.5 metres and 6 metres respectively downstream of the embankment centreline.	The pressure readings from these piezometers are consistent with historical performance dating back to the first filling of the dam in 1988 with the exception of WHV17. Due to damages to the piezometer housing, it is possible that WHV17 readings exceed the trigger level during the January 2011 flood event. After the flood, the piezometers levels have receded, as expected, and fall in line with historical trending.	Any increase in the pressure reading for WHV15 in excess of EL 54 metres should trigger additional monitoring and investigation. Any increase in the pressure reading for WHV17 in excess of EL 47 metres should trigger additional monitoring and investigation.
WVH18 WVH19	These three piezometers are located at EL 55 metres within the embankment	The pressure readings from these piezometers are consistent with historical	Any increase in the pressure reading for WHV19 in excess of EL 58

WVH20	core at Ch 1600. WVH18 is 4 metres upstream of the embankment centreline, WVH19 is on the embankment centreline and WVH20 is 4 metres downstream of the embankment centreline.	performance dating back to the first filling of the dam in 1988. There is nothing to indicate that any of the piezometers have approached the trigger levels for this section.	metres should trigger additional monitoring and investigation.
WVH21 WVH22	These two piezometers are located at EL 65 metres within the embankment core at Ch 1600. WVH21 is 3 metres upstream of the embankment centreline and WVH22 is on the embankment centreline.	The pressure readings from these piezometers are consistent with historical performance dating back to the first filling of the dam in 1988 with the exception of WHV22. Due to damages to the piezometer housing, it is possible that WHV22 readings exceed the trigger level during the January 2011 flood event. After the flood, the piezometers levels have receded, as expected, and fall in line with historical trending.	Any increase in the pressure reading for WHV22 in excess of EL 64.5 metres should trigger additional monitoring and investigation.
WVH23 WVH24	These two piezometers are located at EL 32 metres within the alluvium at Ch 1600. WVH23 is 42 metres upstream of the embankment centreline and WVH24 is 42 metres downstream of the embankment centreline.	As expected, WVH23 is connected directly to the storage and WVH24 is free draining with no apparent connection to the storage. The trigger level should be verified. WHV24 is on the downstream side of the embankment and this trigger level is viewed as abnormally conservative.	Any increase in the pressure reading for WHV24 in excess of EL 64.5 metres should trigger additional monitoring and investigation.
WVH25 WVH26 WVH27	These three piezometers are located within the sandstone foundation at EL 15 metres under the embankment core at Ch 1800. WVH25 is 11 metres upstream of the embankment centreline, WVH26 is on the embankment centreline and WVH27 is 11 metres downstream of the embankment centreline. The grout curtain is located midway between WVH25	The pressure readings from these piezometers are consistent with historical performance dating back to the first filling of the dam in 1988. There is nothing to indicate that any of the piezometers have approached the trigger levels for this section.	Any increase in the pressure reading for WHV26 in excess of EL 35 metres should trigger additional monitoring and investigation.

	and W VH26.		
W VH28 W VH29 W VH30 W VH31 W VH32 W VH33	These six piezometers are located at EL 25 metres within the embankment core and downstream filter at Ch 1800. The piezometers are fairly evenly spaced. W VH28 and W VH29 are within the core, 11 metres and 5 metres respectively, upstream of the embankment centreline. W VH30 is within the core on the embankment centreline. W VH31 and W VH32 are within the core, 5 metres and 9.5 metres respectively downstream of the embankment centreline. W VH33 is within the downstream filter, 13.6 metres downstream of the embankment centreline.	The pressure readings from these piezometers are consistent with historical performance dating back to the first filling of the dam in 1988. It appears that the core has dried out to some extent during the recent drought as there is currently quite a steep pressure drop between W VH28 and W VH29, that is in excess of the levels experienced prior to 2001. This gradient is not of concern and would be expected to reduce over time if the level of the storage remained high.	Any increase in the pressure reading for W VH29 in excess of EL 57 metres should trigger additional monitoring and investigation. Any increase in the pressure reading for W VH32 in excess of EL 36 metres should trigger additional monitoring and investigation.
W VH34 W VH35 W VH36 W VH37	These four piezometers are located at EL 35 metres within the embankment core at Ch 1800. The piezometers are fairly evenly spaced. W VH34 and W VH35 are 8 metres and 3 metres respectively, upstream of the embankment centreline. W VH36 and W VH37 are 3 metres and 8 metres respectively downstream of the embankment centreline.	The pressure readings from these piezometers are consistent with historical performance dating back to the first filling of the dam in 1988 with the exception of W VH37. Due to damages to the piezometer housing, it is possible that W VH37 readings exceed the trigger level during the January 2011 flood event. After the flood, the piezometers levels have receded, as expected, and fall in line with historical trending.	Any increase in the pressure reading for W VH36 in excess of EL 53 metres should trigger additional monitoring and investigation. Any increase in the pressure reading for W VH37 in excess of EL 41 metres should trigger additional monitoring and investigation.
W VH38 W VH39 W VH40 W VH41	These four piezometers are located at EL 45 metres within the embankment core at Ch 1800. The piezometers are fairly evenly spaced. W VH38 and W VH39 are 7.5 metres and 2.5 metres respectively, upstream of the embankment centreline.	The pressure readings from these piezometers are consistent with historical performance dating back to the first filling of the dam in 1988. There is nothing to indicate that any of the piezometers have approached the trigger	Any increase in the pressure reading for W VH39 in excess of EL 59 metres should trigger additional monitoring and investigation. Any increase in the pressure reading for W VH41 in excess of EL 48

	WVH40 and WVH41 are 2.5 metres and 6 metres respectively downstream of the embankment centreline.	levels for this section.	metres should trigger additional monitoring and investigation.
WVH42 WVH43 WVH44	These three piezometers are located at EL 55 metres within the embankment core at Ch 1800. WVH42 is 4 metres upstream of the embankment centreline, WVH43 is on the embankment centreline and WVH44 is 4 metres downstream of the embankment centreline.	The pressure readings from these piezometers are consistent with historical performance dating back to the first filling of the dam in. There is nothing to indicate that any of the piezometers have approached the trigger levels for this section.	Any increase in the pressure reading for WHV44 in excess of EL 57 metres should trigger additional monitoring and investigation.
WVH45 WVH46	These two piezometers are located at EL 65 metres within the embankment core at Ch 1800. WVH45 is 3 metres upstream of the embankment centreline and WVH46 is on the embankment centreline.	The pressure readings from these piezometers are consistent with historical performance dating back to the first filling of the dam in. However the reading from WVH46 appears to be high and the reason for this high reading requires further investigation.	Any increase in the pressure reading for WHV46 in excess of EL 66 metres should trigger additional monitoring and investigation. This is currently occurring and further investigations will be undertaken.
WVH47 WVH48 WVH49	These three piezometers are located at EL 28 metres within the embankment core at around Ch 1960. WVH47 is 10.5 metres upstream of the embankment centreline. WVH48 is on the embankment centreline. WVH49 is 10.5 metres downstream of the embankment centreline.	The pressure readings from these piezometers are consistent with historical performance dating back to the first filling of the dam in. However the reading from WVH49 appears to be triggered and the reason for this high reading requires further investigation.	Any increase in the pressure reading for WHV49 in excess of EL 29 metres should trigger additional monitoring and investigation.
WVH50 WVH51	These two piezometers are located within the embankment core at around Ch 1960. WVH50 is at EL 30 at an unknown distance upstream of the embankment centreline. WVH51 is at EL 34 on the embankment centreline.	The pressure readings from these piezometers are consistent with historical performance dating back to the first filling of the dam in 1988.	No trigger levels are considered valid for these piezometers.

WVH52 WVH53 WVH54 WVH55 WVH56 WVH57	These six piezometers are located between EL 44 and EL 36 at the interface of spillway monolith 52 and the spillway foundations, at Ch 1170. The piezometers are spaced over a distance of approximately 25 metres, with WVH57 being the most upstream piezometer moving sequentially downstream to WVH52, the most downstream piezometer.	The pressure readings from these piezometers are consistent with historical performance dating back to the first filling of the dam in 1988. There is nothing to indicate that any of the piezometers have approached the trigger levels for this section.	Any trend showing an increase in the pressure reading for any piezometer.
WVH58	This piezometer is located at EL 38 at the interface of spillway monolith 53 and the spillway foundations, at Ch 1185 (spillway centreline). The piezometer is located directly under the lower gallery.	The pressure readings from these piezometers are consistent with historical performance dating back to the first filling of the dam in 1988. There is nothing to indicate that any of the piezometers have approached the trigger levels for this section.	Any trend showing an increase in the pressure reading for the piezometer.
WVH59 WVH60 WVH61 WVH62 WVH63 WVH64	These six piezometers are located between EL 44 and EL 38 at the interface of spillway monolith 54 and the spillway foundations, at Ch 1200. The piezometers are spaced over a distance of approximately 25 metres, with WVH64 being the most upstream piezometer moving sequentially downstream to WVH59, the most downstream piezometer.	The pressure readings from these piezometers are consistent with historical performance dating back to the first filling of the dam in 1988. There is nothing to indicate that any of the piezometers have approached the trigger levels for this section.	Any trend showing an increase in the pressure reading for any piezometer.
WVH65	This piezometer is located at EL 39 at the interface of spillway monolith 55 and the spillway foundations, at Ch 1215. The piezometer is located directly under the lower gallery.	The pressure readings from these piezometers are consistent with historical performance dating back to the first filling of the dam in 1988. There is nothing to indicate that any of the piezometers have approached the trigger levels for this section.	Any trend showing an increase in the pressure reading for the piezometer.

8.2 Pore Pressure (Total Pressure Cells)

The Total Pressure Cells were primarily installed to monitor embankment settlement following construction. Collection of data from the Total Pressure Cells appeared to cease in the 1980s and no record on why this decision was made can be found. Additionally, no data records at all can be located.

8.3 Deformation Monitoring

8.3.1 Dam Embankment Deformation

Deformation surveys are undertaken annually at Wivenhoe Dam. The last survey was undertaken after the January 2011 flood and is contained in Appendix B. Following a review of the movements, no values could be found that are cause for any immediate concern. The deformation at this dam is lower than expected for an embankment dam of 56 m in height. The rate of deformation has slowed and has stayed relatively consistent since the end of construction. Annualized summarization of settlement and displacement in relation to the specified time interval for all of the Wivenhoe Dam Embankment Monuments are shown in Figure 5 and Figure 6.




Figure 5 - Wivenhoe Dam Settlement Relative to the Time Interval




Figure 6 - Wivenhoe Dam Displacement Relative to the Time Interval

There are two cross sections of deformation monitoring instrumentation installed at the maximum sections of Wivenhoe Dam. They are located at chainage 1,600 & 1,800. Both of these cross sections were analysed for settlement and displacement amid concerns of the unprecedented hydraulic loading on the dam from the January 2011 flood event. These locations are identified on Figure 7 below.




Figure 7 - Location of monuments analysed for chainages 1,600 and 1,800

i). Embankment Settlement

Figure 8 and Figure 9 present the post construction deformation settlement versus time for both of the previously stated chainages. The maximum values of settlement at the two maximum sections are 138 mm, with an average settlement of 53.6 mm at ch. 1,600 and 43.8 mm at ch. 1,800. To note, the maximum settlement at each of the locations occurred on the upstream edge of the dam crest.




Figure 8 - Settlement of monuments analysed for chainages 1,600




Figure 9 - Settlement of monuments analysed for chainages 1,800

Figure 10 and Figure 11 present the same monument settlement but is displayed as a % of the dam height. This provides an additional tool to analyse the data trending of deformation. This settlement is in line with similar embankment sizes and designs. A point of concern to be noted regarding the settlement monuments WVSS036, WVSS037 at chainage 1,800 and WVSS047 at chainage 1,600. The monuments are located on the downstream slope of the embankment near the dam toe. Within

the last 15 years, these monuments are showing a trending of increasing in elevation. The maximum value of increased elevations of the previous mentioned monuments is 15 mm.




Figure 10 - Settlement of Monuments Analysed for Chainages 1,600




Figure 11 - Settlement of Monuments Analysed for Chainages 1,800

ii). Embankment Displacement

Figure 12 and Figure 13 present the post construction deformation displacement, normal to the dam, versus time for chainages 1,600 and 1,800. The maximum value of displacement, at the two maximum sections is 116 mm, with an average settlement of 25.3 mm at ch. 1,600 and 27.7 mm at ch. 1,800. Similar to the dam settlement, the maximum displacement at each of the chainages occurred at the monuments located on the upstream edge of the dam crest.




Figure 12 - Displacement of Monuments Analysed for Chainages 1,600




Figure 13 - Displacement of Monuments Analysed for Chainages 1,800

Additional results outside of the chainage 1,600 and 1,800, the maximum settlement since the 1990 base survey was 64 mm that was measured at Point 8, which is near the highest section of the embankment. This is in line with other settlements at surrounding points 3 to 12 which are greater than 24 mm. The maximum horizontal movement of 19 mm at point 6 is considered insignificant.

The survey shows that control point No. 109 is displaying significant progressive settlement of 52 mm between 2007 and 2009 and a further 9 mm in 2010. This control point was established on loose material downstream of the embankment following the 2005 spillway upgrade and may need to be re-established. It is recommended that this issue be investigated in conjunction with the 2011 survey.

8.3.2 Fuse Plug Deformation

Deformation surveys are undertaken annually at Wivenhoe Dam. The last survey was undertaken after the January 2011 flood. Following a review of the movements, no values could be found that are cause for any concern. The Wivenhoe Fuse Plugs are a bit over 5 years from construction. There is not a long enough track record to determine a rate of deformation with any consistency.




Figure 14 - Location of monuments Analysed for the Fuse Plug

i). Fuse Plug Settlement

Figure 15 presents the post construction deformation settlement versus time for the fuse plugs. The maximum value of settlement is 15 mm, with an average settlement of 5.8 mm. There is an issue to be investigated for the settlement of all the monuments, WVSSS070 through WVSSS081, that are located on or around the fuse plug. Within the last two plus years, there is a clear trend that the entire structure is gaining in elevation. It can be seen in the following Figure 15 that all the monuments are settling (or rising) at similar rates. A cross-section of the fuse plug design can be found in Appendix A.




Figure 15 - Settlement of Monuments Analysed for Fuse Plug

ii). Fuse Plug Displacement

Figure 16 presents the post construction deformation displacement versus time for the fuse plugs. The maximum value of displacement is 8 mm, with an average of 3.1 mm. With the exception of monument WVSS075, all the monuments are operating as expected. Monument WVSS075 is located in the embankment portion of the middle fuse plug and it should be noted that it has not been trending in line with the other monuments for the last year plus.




Figure 16 - Displacement of Monuments Analysed for Fuse Plug

8.4 Structural Movement (Inclinometers)

A summary of the inclinometer results is shown in the table below. Detailed graphs showing the behaviour of individual inclinometers over time are contained in Appendix C. Plans showing the locations of the inclinometers are shown in Appendix A.

INCLINOMETER	DESCRIPTION	COMMENTS
I1 I2 I3	These three inclinometers are located in the embankment at Ch 1,600. I1 is 6.5 metres downstream of the embankment centreline and is 60 metres in depth. I2 is 40 metres downstream of the embankment centreline is now 18 metres in depth as an old instrument is jammed at this depth. I3 is 68 metres downstream of the embankment centreline and is 24 metres in depth.	Cumulative displacement since the dam was constructed is generally less than 28 millimetres over the length of the inclinometer along the normal axis of the dam. The reading dated 22-Jan-11 (Post Flood) shows a deviation from the trending. This will be monitored and the inclinometer will continue to be read on a monthly basis.
I4	This inclinometer is located in the embankment at Ch 1,800. I4 is 6.5 metres downstream of the embankment centreline and is 68 metres in depth.	Cumulative displacement since the dam was constructed is generally less than 20 millimetres over the length of the inclinometer along the normal axis of the dam. The reading dated 22-Jan-11 (Post Flood) shows a deviation from the trending. This will be monitored and the inclinometer will continue to be read on a monthly basis.

8.5 Seepage

The seepage weirs were inundated during the January 2011 flooding event. No data was recorded. Plans showing the locations of the seepage points are shown in Appendix A.

8.6 Post Tensioning

Post tensioning analysis has not been conducted since the January 2011 flood event. As noted in the 2009 Annual Inspection, most of the posts tensioning anchors were load tested in 2009 in accordance with ANCOLD guidelines.

9 CONCLUSIONS

In January 2011, Wivenhoe Dam experienced the flood of record for the post construction era. During this flood event, the storage level reached approximately EL75, or more than 4 m above the previous post construction flood of record. occurrence in 1999. This represented a first fill for the upper part of the two main dam embankments, two saddle dam embankments, and the fuse plug embankments. The fuse plug embankments were installed in 2004 / 2005 in the auxiliary spillway.

During the flood event, the flow rate released from Wivenhoe Dam Spillway peaked at approximately 7,500 m³/s. The area directly downstream of the Wivenhoe Dam Spillway had significant erosion and scour damage to the plunge pool, outlet discharge channel, lower dam access roads and spillway lookout recreational area. Initial estimates of the volume of the rock eroded from the plunge pool are over 25,000 m³ of material. In particular, several boulders in excess of 700 tons have been displaced and deposited downstream.

It is concluded from a review of the design and monitoring data available for the dam that:

1. During the 2011 flood event, the dam performed as designed.
2. The erosion of the plunge pool was anticipated during the design of the dam, but it was not quantified at that time due to the difficulty of modelling the erosive processes. The initial excavated plunge pool was based on an assumed flow of 5,000 m³/s and was intended to limit erosion from the downstream end of the spillway chute.
3. Erosion was predicted to occur for large floods, even with the pre-excavated plunge pool. However the predicted erosion would not impact the safety of the dam. As part of the original design, the concrete apron on the downstream end of the flip bucket was constructed to minimise the risk to uncontrollable head cutting to the toe of the flip bucket.
4. Although there was significant scour of the pre-excavated plunge pool particularly in downstream sloping face, observations also appear to show that the stability of the valley slopes and the foundation of the dam and spillway have not been compromised and are in a safe condition with rock scouring not resulting in head cutting back to the flip bucket toe and its sloping apron.
5. The deformation survey of the dam did not show any significant movements of the dam embankment following the flood event.
6. The post flood piezometer readings do not show any significant changes in the internal pore pressures of the dam.
7. Due to the elevated tail waters during the flood event it was not possible to monitor the seepage through the embankment. Post flood readings do not indicate any significant change in the seepage from the dam.
8. An analysis of the instrumentation monitoring data highlighted a few items to be aware of during future reviews.

10 RECOMMENDATIONS

The following recommendations are made from this review. It should be noted that a consultancy has already been initiated to investigate the spillway plunge pool and evaluate the need for further remedial works. The consultant's review and recommendations are not incorporated into this report at this time.

<u>Issue</u>	<u>Recommendations</u>
Erosion and scour damage to the plunge pool and downstream spillway chute.	1. Investigate options to open a channel through the rock deposited by the erosion in the spillway outlet channel in order to restore the ability to operate the FDC Valve without cavitation and improve the efficiency of the hydro power station. 2. Investigate the performance of the spillway dissipator following the enlarging of the plunge pool to ensure that safe operation can occur for the full range of flood events. In particular, analyse recirculation flows in the plunge pool which may lead to erosion of the side walls or the head cutting of the upstream rock face. 3. Reestablishment of the water measurement weir to help regulate outflow rates for water delivery purposes.
Damage to the side walls of the spillway outlet channel	4. Carry out a safety assessment of the side wall of the spillway chute and the lookout structure and assess the need for any remedial works where weak joints have been eroded.
Damage to the access ladders and bench road from the spillway discharges.	5. Investigate options to reinstate maintenance access to the concrete bench above the hydro power station. 6. Repair the ladders and access platforms damaged by the spillway flows to restore safe access to the FDC dissipator chamber and the hydropower station.
Damage to the recreation facilities	7. Investigate options to repair the damage to the recreation areas and access roads including the road embankment leading to the spillway lookout. 8. Reinstall fencing and other safety barriers along the edges of the spillway chute. 9. Batter back vertical cuts in the soil profile to a safe slope and protect the face of the batters from further erosion during rain events.
Some piezometers have reached the nominated trigger levels – inconsistency in piezometric levels.	10. Changes in the piezometer levels should be reviewed and the impact on stability assessed. Validate and possibly re-establish the trigger levels. 11. The piezometer lines should be flushed given the inundation of the piezometer hut during the January 2011 flood event.


	12. The piezometer data should be reviewed monthly to assess any further changes in pressures.
Data was not recorded during the flood due to the inability to access the piezometer huts at the toe of the main embankment.	13. Repair gauge boards and consider the feasibility of remote monitoring of the piezometer gauges during flood events.
Settlement monuments WVSS036, WVSS037 at chainage 1800 and WVSS047 at chainage 1600 are increasing in height (approximately 15 mm).	14. The monuments are located on downstream slope of the embankment near the dam toe. Within the last 15 years, these monuments are showing a reversing trend and are increasing in elevation. The maximum value of increased elevations of the previous mentioned monuments is 15 mm. The annual surveys should be continued and if the trends identified continue further analysis will be undertaken into the deformation of the dam.
Settlement of all the monuments, WVSS070 through WVSS081. Within the last two plus years, there is a clear trend that the entire structure is gaining in elevation. All the monuments are settling (or rising) at similar rates.	15. The network of survey monuments should be checked at the next annual survey to confirm that the apparent increase in elevation is actually occurring. 16. Following confirmation of the accuracy of the survey, investigate the upwards tend to determine the cause for the abnormal settlement trending.
All four of the inclinometer cumulative displacement plots show dam movement in the normal (downstream) direction that is inconsistent.	17. Review the inclinometer readings at the next annual inspection with a particular emphasis placed on the incremental changes in the reading over the preceding 12 months.


11 REFERENCES


- (DPI Water Commercial 1995) "Wivenhoe Dam Design Report", September 1995.
- (GHD, 1997) "Wivenhoe Dam Safety Review", April 1997.
- (SunWater) "Detailed Stability Check of the Spillway Wall Monoliths at Wivenhoe Dam", June 2001.
- (SunWater 2001) "Assessment of Piping Potential in the Wivenhoe Saddle Dams", November 2001.
- (Wivenhoe Alliance 2005) "Wivenhoe Upgrade Design and Construction Report", December 2005.
- (Glen Hobbs and Associates 2006) "Wivenhoe Dam Radial gate Trunnion Bearings Review", May 2006.
- (NSW Department of Commerce 2006) "Wivenhoe Dam Comprehensive Inspection Draft Report", July 2006.
- (Seqwater 2009) "Wivenhoe Dam – Emergency Action Plan, September 2009.
- (Seqwater 2009) "Wivenhoe Dam – Standing Operating Procedures, March 2009.
- (Seqwater 2009) "Wivenhoe Dam – Operation and Maintenance Manuals, March 2009.
- (GHD 2009) "Report for Raising Wivenhoe Dam Full Supply Level Review", December 2009.
- (URS 2009) Dartmouth Dam- Appendix B Deformation Analysis
- (Seqwater, 2011) "January 2011 Flood Event- Report on the operation of Somerset and Wivenhoe Dam", March 2011.
- (DERM, 2011) "Wivenhoe Dam Spillway Development, s.37 Consultation, RTI Act 2009, DERM Application No. 10-207" Russ McConnell, Manager Containment System, OWSR



APPENDIX A DRAWINGS



DRAFT













WIVENHOE DAM STAGE 1 WORKS RIGHT ABUTMENT SPILLWAY GENERAL ARRANGEMENT		WIVENHOE DAM STAGE 1 WORKS RIGHT ABUTMENT SPILLWAY GENERAL ARRANGEMENT WIVENHOE DAM STAGE 1 WORKS RIGHT ABUTMENT SPILLWAY GENERAL ARRANGEMENT	
WIVENHOE DAM STAGE 1 WORKS RIGHT ABUTMENT SPILLWAY GENERAL ARRANGEMENT WIVENHOE DAM STAGE 1 WORKS RIGHT ABUTMENT SPILLWAY GENERAL ARRANGEMENT	WIVENHOE DAM STAGE 1 WORKS RIGHT ABUTMENT SPILLWAY GENERAL ARRANGEMENT WIVENHOE DAM STAGE 1 WORKS RIGHT ABUTMENT SPILLWAY GENERAL ARRANGEMENT	WIVENHOE DAM STAGE 1 WORKS RIGHT ABUTMENT SPILLWAY GENERAL ARRANGEMENT WIVENHOE DAM STAGE 1 WORKS RIGHT ABUTMENT SPILLWAY GENERAL ARRANGEMENT	WIVENHOE DAM STAGE 1 WORKS RIGHT ABUTMENT SPILLWAY GENERAL ARRANGEMENT WIVENHOE DAM STAGE 1 WORKS RIGHT ABUTMENT SPILLWAY GENERAL ARRANGEMENT



APPENDIX B January 2011 Spillway Survey

DRAFT




Level Datum: A.M.L. Based on FID4342 @ EL. 742.764 m.
 Co-ordinate Datum: Plane A.M.C. based on Pillars W & W7.


PILLAR W

Point	Ass. Siding	Northings	Eastings	Description
1	489457.845	644728.244	772248.14	772248.14
2	489457.845	644728.244	772248.14	772248.14
3	489457.845	644728.244	772248.14	772248.14
4	489457.845	644728.244	772248.14	772248.14
5	489457.845	644728.244	772248.14	772248.14
6	489457.845	644728.244	772248.14	772248.14
7	489457.845	644728.244	772248.14	772248.14
8	489457.845	644728.244	772248.14	772248.14
9	489457.845	644728.244	772248.14	772248.14
10	489457.845	644728.244	772248.14	772248.14

BRISBANE RIVER - AMTD 150.2KM WIVENHOOE DAM SPILLWAY PLUNGE POOL TOPOGRAPHIC SURVEY		PROJECT NUMBER A3-218152 DATE 2015
SURVEY DATE 2015		DRAWN BY [Redacted] CHECKED BY [Redacted]
SCALE 1:500		PROJECT LOCATION [Redacted]
PROJECT DESCRIPTION [Redacted]		PROJECT STATUS [Redacted]



SECOWATER WIVENHOE DAM SPILLWAY CHANNEL SURVEY 22 JAN 2011 CONTOUR PLAN		CONTRACT NUMBER 238120
SCALE (AS SHOWN) 0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150 160 170 180 190 200 210 220 230 240 250 260 270 280 290 300 310 320 330 340 350 360 370 380 390 400 410 420 430 440 450 460 470 480 490 500 510 520 530 540 550 560 570 580 590 600 610 620 630 640 650 660 670 680 690 700 710 720 730 740 750 760 770 780 790 800 810 820 830 840 850 860 870 880 890 900 910 920 930 940 950 960 970 980 990 1000		DATE 22 JAN 2011
MAP INFORMATION Coordinate System: MGA84 Zone 56		DATE 22 JAN 2011
SCALE (AS SHOWN) 0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150 160 170 180 190 200 210 220 230 240 250 260 270 280 290 300 310 320 330 340 350 360 370 380 390 400 410 420 430 440 450 460 470 480 490 500 510 520 530 540 550 560 570 580 590 600 610 620 630 640 650 660 670 680 690 700 710 720 730 740 750 760 770 780 790 800 810 820 830 840 850 860 870 880 890 900 910 920 930 940 950 960 970 980 990 1000		DATE 22 JAN 2011
SCALE (AS SHOWN) 0 10 20 30 40 50 60 70 80 90 100 110 120 130 140 150 160 170 180 190 200 210 220 230 240 250 260 270 280 290 300 310 320 330 340 350 360 370 380 390 400 410 420 430 440 450 460 470 480 490 500 510 520 530 540 550 560 570 580 590 600 610 620 630 640 650 660 670 680 690 700 710 720 730 740 750 760 770 780 790 800 810 820 830 840 850 860 870 880 890 900 910 920 930 940 950 960 970 980 990 1000		DATE 22 JAN 2011



REFERENCE MARKS				
POINT	EAST	NORTH	ELEV	NAME
783618	461377.438	6969676.488	63.549	KEO Star Picket
2003401	461860.158	6969773.518	60.486	KEO Star Picket
WT	460603.643	6969943.178	58.674	KEO Pile



Scale 1:2000 - lengths are in Metres.

20 0 20 40 60 80 100 120 140 160 180 200 220 240 260 280

3D VIEW
SEE SHEET 2

Project No.		102271001	
Date	15/08/11	Drawn by	CH/MLL
Scale		H 1:2000	
V Datum	AHD (DA)	Contour Int.	0.25m
V Contour	BM 20020401	RL	60.428m
H Contour PLAN: REC BASED ON MDA VER 1.0			
Local Authority: BRISBANE CITY COUNCIL			
Surveyed	BL	Date	25/05/2011
Drawn	BL	Date	15/08/2011
File No	102271002	File	CSJ
SHEET 1 OF 2			

North Surveys PTY LTD
Creating exceptional value

This Project: WIVENHOE DAM SPILLWAY
BRISBANE VALLEY HIGHWAY
Client: SMEC Australia Pty Ltd


Day: 102271#001 Rev: 0





APPENDIX C INSTRUMENTATION DATA

DRAFT


Wivenhoe Dam Piezo Levels @ CH1600 & EL ~15
(WVH01 @ 11.0 U/S; WVH02 @ 0.0; WVH03 @ 11.0 D/S)
 (All distances and elevations are in metres. All levels to AHD.)








Wivenhoe Dam Piezo Levels@ CH1600 & EL ~45
(WVH14 @ 7.5 U/S; WVH15 @ 2.5 U/S; WVH16 @ 2.5 D/S; WVH17 @ 6.0 D/S)
(All distances and elevations are in metres. All levels to AHD.)



Wivenhoe Dam Piezo Levels@ CH1600 & EL ~55

(WVH18 @ 4.0 U/S; WVH19 @ 0.0; WVH20 @ 4 D/S)


(All distances and elevations are in metres. All levels to AHD.)




Wivenhoe Dam Piezo Levels@ CH1600 & EL ~65


(WVH21 @ 3.0 U/S; WVH22 @ 3 D/S)


(All distances and elevations are in metres. All levels to AHD.)




Wivenhoe Dam Piezo Levels@ CH1800 & EL ~15
 (WVH25 @ 11.0 U/S; WVH26 @ 0.0; WVH27 @ 11 D/S
 (All distances and elevations are in metres. All levels to AHD.)








Wivenhoe Dam Piezo Levels @ CH1800 & EL ~45
 (WVH38 @ 7.5 U/S; WVH39 @ 2.5 U/S; WVH40 @ 2.5 D/S; WVH41 @ 6.0 D/S
 (All distances and elevations are in metres. All levels to AHD.)




Wivenhoe Dam Piezo Levels@ CH1800 & EL ~55
(WVH42 @ 4.0 U/S; WVH43 @ 0.0; WVH44 @ 4 D/S
(All distances and elevations are in metres. All levels to AHD.)



Wivenhoe Dam Piezo Levels@ CH1800 & EL ~65

(WVH45 @ 3.0 U/S; WVH46 @ 0.0)


(All distances and elevations are in metres. All levels to AHD.)



Wivenhoe Dam Piezo Levels @ ~CH1965 & EL ~27.5 in diversion channel for construction


(WVH47 @ 10.5 U/S; WVH48 @ 0 U/S; WVH49 @ 10.5 D/S)

(All distances and elevations are in metres. All levels to AHD.)




Wivenhoe Dam Piezo Levels WWH50 and WWH51 in diversion channel for construction

(All distances and elevations are in metres. All levels to AHD.)




Wivenhoe Dam Piezo Levels @ Mono S2
WVH52, WVH53, WVH54, WVH55 @ EL ~36; WVH56 @ EL ~38; WVH57 @ EL ~44
 (All distances and elevations are in metres. All levels to AHD.)




Wivenhoe Dam Piezo Levels at Mono S3 - WWH58 @ EL ~ 37

(All distances and elevations are in metres. All levels to AHD.)




Wivenhoe Dam Piezo Levels @ Mono S4
WVH59, WVH60, WVH61, WVH62 @ EL ~38; WVH63 @ EL ~44
 (All distances and elevations are in metres. All levels to AHD.)



Wivenhoe Dam Piezo Levels at Mono S5 - WWH65 @ EL ~39

(All distances and elevations are in metres. All levels to AHD.)




RST Instruments Ltd.

Borehole : I1
Project : Wivenhoe
Location :
Northing :
Easting :
Collar :

CUMULATIVE DISPLACEMENT

Inclinanalysis v.2.35

Spiral Correction : N/A
Collar Elevation : 79.1 meters
Borehole Total Depth : 59.5 meters
North Groove Azimuth :
Base Reading : 1989 Aug 30 11:01
Axis A Azimuth : 0.0 degrees




RST Instruments Ltd.

CUMULATIVE DISPLACEMENT

Inclinanalysis v.2.35

Borehole : IZ
Project : Wivenhoe
Location :
Northing :
Easting :
Collar :
Spiral Correction : N/A
Collar Elevation : 55.8 meters
Borehole Total Depth : 17.0 meters
North Groove Azimuth :
Base Reading : 1989 Aug 30 11:01
Axis A Azimuth : 0.0 degrees




RST Instruments Ltd.

Borehole : B
Project : Wivenhoe
Location :
Northing :
Easting :
Collar :

CUMULATIVE DISPLACEMENT

Inclinanalysis v.2.35

Spiral Correction : N/A
Collar Elevation : 42.9 meters
Borehole Total Depth : 23.5 meters
North Groove Azimuth :
Base Reading : 1990 Jan 12 11:01
Axis A Azimuth : 0.0 degrees




RST Instruments Ltd.

CUMULATIVE DISPLACEMENT

Inclinanalysis v.2.35

Borehole : M
Project : Wivenhoe
Location :
Northing :
Easting :
Collar :

Spiral Correction : N/A
Collar Elevation : 79.1 meters
Borehole Total Depth : 57.0 meters
North Groove Azimuth :
Base Reading : 1900 Jan 09 11:01
Axis A Azimuth : 0.0 degrees




RST Instruments Ltd.

Borehole : LHI1
Project : Wivenhoe
Location :
Northing :
Easting :
Collar :

CUMULATIVE DISPLACEMENT

Inclanalysis v.2.35

Spiral Correction : N/A
Collar Elevation : 0.0 meters
Borehole Total Depth : 18.5 meters
North Groove Azimuth :
Base Reading : 2010 Apr 30 10:50
Axis A Azimuth : 0.0 degrees




RST Instruments Ltd.

Borehole : LH2
Project : Wivenhoe
Location :
Northing :
Easting :
Collar :

CUMULATIVE DISPLACEMENT

Inclinanalysis v.2.35

Spiral Correction : N/A
Collar Elevation : 0.0 meters
Borehole Total Depth : 18.0 meters
North Groove Azimuth :
Base Reading : 2010 Apr 27 13:30
Axis A Azimuth : 0.0 degrees




RST Instruments Ltd.

Borehole : LH3
Project : Wivenhoe
Location :
Northing :
Easting :
Collar :

CUMULATIVE DISPLACEMENT

Inclinanalysis v.2.35

Spiral Correction : N/A
Collar Elevation : 0.0 meters
Borehole Total Depth : 16.5 meters
North Groove Azimuth :
Base Reading : 2010 Apr 27 13:53
Axis A Azimuth : 0.0 degrees




RST Instruments Ltd.

Borehole : RH11
Project : Wivenhoe
Location :
Northing :
Easting :
Collar :

CUMULATIVE DISPLACEMENT

Inclinanalysis v.2.35

Spiral Correction : N/A
Collar Elevation : 0.0 meters
Borehole Total Depth : 21.5 meters
North Groove Azimuth :
Base Reading : 2010 Apr 30 10:09
Axis A Azimuth : 0.0 degrees




RST Instruments Ltd.

Borehole : RH2
Project : Wivenhoe
Location :
Northing :
Easting :
Collar :

CUMULATIVE DISPLACEMENT

Inclinanalysis v.2.35

Spiral Correction : N/A
Collar Elevation : 0.0 meters
Borehole Total Depth : 22.5 meters
North Groove Azimuth :
Base Reading : 2010 Apr 27 14:37
Axis A Azimuth : 0.0 degrees




RST Instruments Ltd.

Borehole : I1
Project : Wivenhoe
Location :
Northing :
Easting :
Collar :

ABSOLUTE POSITION

Inclinanalysis v.2.35

Spiral Correction : N/A
Collar Elevation : 79.1 meters
Borehole Total Depth : 59.3 meters
North Groove Azimuth :
Base Reading : 1989 Aug 30 11:01
Axis A Azimuth : 0.0 degrees




RST Instruments Ltd.

Borehole : I2
 Project : Wivenhoe
 Location :
 Northing :
 Easting :
 Collar :

ABSOLUTE POSITION

Inclanalysis v.2.35

Spiral Correction : N/A
 Collar Elevation : 55.3 meters
 Borehole Total Depth : 17.0 meters
 North Groove Azimuth :
 Base Reading : 1989 Aug 30 11:01
 Axis A Azimuth : 0.0 degrees




RST Instruments Ltd.

Borehole : B
 Project : Wivenhoe
 Location :
 Nothing :
 Easting :
 Collar :

ABSOLUTE POSITION

Inclinanalysis v.2.35

Spiral Correction : N/A
 Collar Elevation : 42.9 meters
 Borehole Total Depth : 23.5 meters
 North Groove Azimuth :
 Base Reading : 1990 Jan 12 11:01
 Axis A Azimuth : 0.0 degrees




RST Instruments Ltd.

Borehole : H
Project : Wivenhoe
Location :
Northing :
Easting :
Collar :

ABSOLUTE POSITION

Inclanalysis v.2.35

Spiral Correction : N/A
Collar Elevation : 79.1 meters
Borehole Total Depth : 57.0 meters
North Groove Azimuth :
Base Reading : 1990 Jan 09 11:01
Axis A Azimuth : 0.0 degrees




RST Instruments Ltd.

Borehole : LH1
 Project : Wivenhoe
 Location :
 Northing :
 Easting :
 Collar :

ABSOLUTE POSITION

Inclinanalysis v.2.35

Spiral Correction : N/A
 Collar Elevation : 0.0 meters
 Borehole Total Depth : 18.5 meters
 North Groove Azimuth :
 Base Reading : 2010 Apr 30 10:50
 Axis A Azimuth : 0.0 degrees



RST Instruments Ltd.


Borehole : LH2
 Project : Wivenhoe
 Location :
 Northing :
 Easting :
 Collar :

ABSOLUTE POSITION


Inclinanalysis v.2.35

Spiral Correction : N/A
 Collar Elevation : 0.0 meters
 Borehole Total Depth : 18.0 meters
 North Groove Azimuth :
 Base Reading : 2010 Apr 27 13:30
 Axis A Azimuth : 0.0 degrees

Axis - A



Axis - B




RST Instruments Ltd.

Borehole : LH3
Project : Wivenhoe
Location :
Northing :
Easting :
Collar :

ABSOLUTE POSITION

Inclanalysis v.2.35

Spiral Correction : N/A
Collar Elevation : 0.0 meters
Borehole Total Depth : 16.5 meters
North Groove Azimuth :
Base Reading : 2010 Apr 27 13:53
Axis A Azimuth : 0.0 degrees




RST Instruments Ltd.

Borehole : RH1
 Project : Wivenhoe
 Location :
 Northing :
 Easting :
 Collar :

ABSOLUTE POSITION

Inclanalysis v.2.35

Spiral Correction : N/A
 Collar Elevation : 0.0 meters
 Borehole Total Depth : 21.5 meters
 North Groove Azimuth :
 Base Reading : 2010 Apr 30 10:09
 Axis A Azimuth : 0.0 degrees



RST Instruments Ltd.


ABSOLUTE POSITION

Inclinanalysis v.2.35


Borehole : RH2
Project : Wivenhoe
Location :
Northing :
Easting :
Collar :

Spiral Correction : N/A
Collar Elevation : 0.0 meters
Borehole Total Depth : 22.5 meters
North Groove Azimuth :
Base Reading : 2010 Apr 27 14:37
Axis A Azimuth : 0.0 degrees

Axis - A



Axis - B



RST Instruments Ltd.

Borehole : RH3
Project : Wivenhoe
Location :
Northing :
Easting :
Collar :



ABSOLUTE POSITION

Inclanalysis v.2.35

Spiral Correction : N/A
Collar Elevation : 0.0 meters
Borehole Total Depth : 22.0 meters
North Groove Azimuth :
Base Reading : 2010 Apr 27 15:08
Axis A Azimuth : 0.0 degrees

Axis - A

Axis - B




RST Instruments Ltd.

Borehole : RH3
Project : Wivenhoe
Location :
Northing :
Easting :
Collar :


CUMULATIVE DISPLACEMENT

Inclinanalysis v.2.35


Spiral Correction : N/A
Collar Elevation : 0.0 meters
Borehole Total Depth : 22.0 meters
North Groove Azimuth :
Base Reading : 2010 Apr 27 15:08
Axis A Azimuth : 0.0 degrees




Settlement (Embankment Cross-Section Chainage 1800)




Settlement (Embankment Cross-Section Chainage 1600)




Settlement (Embankment Cross-Section Chainage 1800)




Settlement (Embankment Cross-Section Chainage 1600)




Displacement (Embankment Cross-Section Chainage 1800)




Displacement (Embankment Cross-Section Chainage 1600)




Settlement Fuse Plug



Displacement Fuse Plug



DRAFT



This plan is based on Survey Map BBQ11732 but scaled as follows:

- lengths $\times 0.2$ to convert to metres
- angles -4° to convert to T

Location of mast & buildings are approximate to fit the site.



ISS				ORIGIN		BY	DATE	DESIGN CHK	DRG CHK	REVISION DETAILS		TITLE	ORIGIN:		DRAWING No	
5				rp			18.10.06			Proposed and Future Commercial DTV Installations Updated		 BROADCAST AUSTRALIA PASSCHENDAELE RIDGE, QLD SITE NO 4114 SITE LAYOUT	DRAWN:			
7				BAPL		jcb	26.05.08			INTEGRATED JJJ SATELLITE DISH REPOINTING PROPOSAL			DESIGN CHK:			
8				BAPL		A.H.	04.06.09			ABC JJJ SATELLITE DISH REPOINTING AS BUILT			DRG CHK:			
9							19.03.10			ERGON ENERGY EQUIPMENT SHELTER PROPOSAL			APPROVED			
10						jcb	14.09.10			ERGON ENERGY EQUIPMENT SHELTER AS BUILT			FOR ISSUE:		BA4114.5	

Wivenhoe Dam Spillway Development

Design Philosophy

Wivenhoe Dam contains a gate controlled flip bucket spillway which throws discharging water away from the dam into a plunge pool for energy dissipation. The plunge pool is a cavity in the sandstone rock downstream and away from the dam. It was recognised at the time of the design that discharges from the dam will enlarge the plunge pool with time. Eventually the plunge pool will enlarge itself to the extent that it becomes stable, with all the discharge energy being dissipated in the cavity by the interaction of the upward flowing water leaving the plunge pool and the water being flipped off the spillway.

Background

The initial arrangement of the spillway was developed by the application of Engineering Principles. The arrangement was then validated by physical modelling in a hydraulic laboratory. The 1 in 200 modelling used erodible material in the plunge pool area. It showed that a plunge pool cavity would form, however erodability cannot be reliably modelled. The final extent of the erosion was however not dependent on the initial size or shape of the plunge pool cavity. On this basis an initial plunge pool was provided in the spillway during the construction of the dam. The constructed bed level of the plunge pool was at RL 17. The discharges of the 1999 flood event lowered the bed level to RL 16.

During the January flood of 2011, the maximum discharge through the spillway of Wivenhoe Dam was $7450 \text{ m}^3/\text{s}$, which is considerably larger than any previous discharges.

Observation

The flood surcharge in Wivenhoe Dam was progressively discharged through the spillway at progressively decreasing rates culminating in the final closure of all gates at 12 noon on the 19th January 2011.

As the tail water receded, a bank (Figure 1) of large blocks of sandstone rock emerged just downstream of the plunge pool. The bank was causing an afflux of about 4 meters.




Figure 1 Plunge Pool 10 am 19/1/2011

The plunge pool drained quickly following final closure exposing more blocks. Immediately before the commencement of operational releases through a crest gate, the full extent of the bank was visible (Figure 2). The sandstone blocks were across the whole width of the spillway, including the low flow channel on the left hand side of the spillway.

Expectations

With the record discharge through the spillway, additional enlargement of the plunge pool cavity was expected. The previous erosion episodes of earlier discharges have resulted in the deposition of moderate sandstone boulders downstream. The higher energy situation has obviously raised and displaced much larger sandstone blocks, which have been deposited in a bank once out of the high energy zone of the plunge pool (Figures 3 & 4).

The expectation is that the sandstone blocks in the bank have come from the floor of the plunge pool cavity, with a substantial lowering of the plunge pool floor.

SEQWater were arranging for diving contractors to examine the plunge pool erosion on the 20th January. The contractors arrived on the site whilst I was there and arranged with SEQWater to undertake the underwater inspection and a bathymetric survey on the 20th.

Issues

The issues are that the sandstone blocks in the bank could have come from elsewhere in the spillway channel, namely:

1. by lateral expansion of the plunge pool cavity at depth to beneath the walls of the spillway, thus decreasing their stability; or
2. by head ward erosion of the plunge pool cavity upstream towards or to beneath the apron and flip of the spillway structure.

Actions

To establish certainty, SEQWater are to:

1. Undertake a bathymetric survey of the plunge pool floor by a depth gauge attached to a boat starting on 20th January 2011; and
2. Investigate lateral expansion extent (if any) by professional divers in the spillway walls and the spillway toe starting 20th January 2011.

OWSR will continue to liaise with SEQWater on the outcomes of the investigations.



Figure 2 Plunge Poole 1 pm 19/1/2011



Figure 3 Sandstone Block Bank from downstream



Figure 4 Sandstone Block Bank just Upstream

Inspection and Report by

Russ McConnell
Manager Containment System, OWSR
Department of Environment and Resource Management.

Allen Peter

From: Allen Peter
Sent: Friday, 18 March 2011 2:19 PM
To: 'Jim Pruss'
Cc: Tibaldi, John (Business Fax); T.Malone [REDACTED] Rob Ayre
(Rob.Ayre [REDACTED]); Guppy Ron; Reilly Bob
Subject: Outcomes of North Pine Dam Meeting 18th March 2011

Jim,

Just to confirm the outcomes of our meeting this morning in relation to North Pine Dam ...

The principal outcome was that Seqwater will prepare a program of activities that they intend to undertake to determine the following issues (which have arisen out of the January flood event) and provide DERM Dam Safety a copy of this program.

- Essentially what is required is a review of the spillway adequacy of North Pine Dam given the experiences during this recent event
This will probably include assessments of:
 - A review of the AEP of the rainfall events (some idea of the representativeness of the gauged rainfalls might be good [from my perspective] and this might be obtained from a review of the weather radar imagery?)
 - A review of the hydrological models used to estimate historical and design flood inflows – recalibration for major floods using updated flood and dam characteristics
 - A review of the accuracy of the gate rating curves (especially at major gate openings) ... Do they adequately take into account: the bridge deck, the instability at major gate openings, the 3D effects of the 5 gate openings etc.?
 - A review of the storage capacity curve (again especially at higher storage levels)
 - A review of the structural adequacy of the gates, piers etc. in terms of whether they can support the higher loads associated with major floods which are in excess of the original design floods.
 - What is the maximum headwater level able to be accommodated within the dam?
 - Are there any operational restrictions that need to be applied to flood operations at the dam?
- A review of the operational procedures ... such as number of gate openings achievable in peak periods, the impact of loss of ability to control gates e.g. when water levels reach switch gear etc., what happens when gates are overtopped, reliability of gate winching mechanisms?
- Whether there should be changes to the Manual in the short term before the outcomes of these studies are known? I am especially thinking of the rapidity of gate movements (e.g. should we reduce the number of opening segments), reliability of gate lifting mechanisms etc.
- The benefit/cost of lowering FSL ... either permanently or temporarily??

Ultimately, I would be looking for some relatively simple short term actions that could provide some benefit and then when the other studies are undertaken, I would be looking for a longer term resolution. I see the short term as 'in the next month or so' and the longer term as 'before the next wet season'. One of the issues that I am particularly keen to obtain is an estimate of the AEP of the flood event that the dam can currently safely pass. This assist in the briefing of Ministers etc.

I am happy for the program to reflect uncertainty in that it may need to be adjusted depending on what is found.

Let me know if you are happy with the above. If not, I am prepared to negotiate a consensus but I look forward to hearing from next week.

Peter Allen

Director Dam Safety (Water Supply)
Office of the Water Supply Regulator

Telephone [REDACTED]

Email peter.allen [REDACTED]



www.derm.qld.gov.au

Department of Environment and Resource Management
3rd Floor 41 George Street, Brisbane Q 4000
GPO Box 2454, Brisbane Q 4001

The information in this email together with any attachments is intended only for the person or entity to which it is addressed and may contain confidential and/or privileged material. Any form of review, disclosure, modification, distribution and/or publication of this email message is prohibited, unless as a necessary part of Departmental business. If you have received this message in error, you are asked to inform the sender as quickly as possible and delete this message and any copies of this message from your computer and/or your computer system network.

Table comparing comments made by DERM and sent to Seqwater by email 13 October 2009 (Annexure 18 and 19 to Statement of Ronald Guppy) that were not incorporated into final version of Seventh Revision of Wivenhoe Flood Mitigation Manual
Prepared by Queensland Floods Commission staff

No. in Annexure 19	Suggestion by DERM (Annexure 18 and 19 to Statement of Ronald Guppy)	Final version of Seventh Revision of Wivenhoe Flood Mitigation Manual (Exhibit 21)
3	Section 8.4 talks about the strategy being chosen based on predictions, maximums and peaks as below: <i>The strategy chosen at any point in time will depend on the following predictions which are to be made using the best forecast rainfall and stream flow information available at the time:</i> • Maximum storage levels in Wivenhoe and Somerset Dams. • Peak flow rate at the Lowood Gauge (excluding Wivenhoe Dam releases). • Peak flow rate at the Moggill Gauge (excluding Wivenhoe Dam releases). Our understanding is that the actual values are used to select W1 to W4 with some variations allowed for based on forecasts. e.g. You transition from W1 to W2 or W3 once the water level in Wivenhoe exceeds EL 68.5m. The choice between W2 and W3 is made on the forecast of the peaks depending on whether the Lowood or the Moggill flows control.	Section 8.4 states: The strategy chosen at any point in time will depend on the actual levels in the dams and the following predictions, which are to be made using the best forecast rainfall and stream flow information available at the time: • Maximum storage levels in Wivenhoe and Somerset Dams. • Peak flow rate at the Lowood Gauge (excluding Wivenhoe Dam releases). • Peak flow rate at the Moggill Gauge (excluding Wivenhoe Dam releases).
Response	As the event proceeds, the forecast maximum storage levels are revised using the actual storage levels as the 'starting' point. Therefore it is appropriate that the 'actual dam levels' are referred to.	

No. in Annexure 19	Suggestion by DERM (Annexure 18 and 19 to Statement of Ronald Guppy)	Final version of Seventh Revision of Wivenhoe Flood Mitigation Manual (Exhibit 21)
4	From this perspective, it may be better to change the figure on page 27 to something along the following lines. Wivenhoe Flood Strategy Flow Chart  <pre> graph TD Start([Start]) --> Q1{Is Wivenhoe level greater than EL 68.5 m?} Q1 -- No --> W1([Use Strategy W1]) Q1 -- Yes --> Q2{Is Wivenhoe level greater than EL 74.0 m?} Q2 -- Yes --> W4([Use Strategy W4]) Q2 -- No --> Q3{Is forecast maximum flow at Lowwood likely to exceed 3,500 m³/sec?} Q3 -- Yes --> W3([Use Strategy W3]) Q3 -- No --> W2([Use Strategy W2]) </pre>	Flow chart on page 23: WIVENHOE FLOOD STRATEGY FLOW CHART  <pre> graph TD Start([START]) --> Q1{Is Wivenhoe level likely to exceed EL 68.5 m?} Q1 -- No --> W1([Use Strategy W1]) Q1 -- Yes --> Q2{Is Wivenhoe level likely to exceed EL 74.0 m?} Q2 -- Yes --> W4([Use Strategy W4]) Q2 -- No --> Q3{Is the maximum flow at Lowwood likely to be less than 3500 m³/s AND the maximum flow at Moggill likely to be less than 4000 m³/s?} Q3 -- Yes --> W2([Use Strategy W2]) Q3 -- No --> W3([Use Strategy W3]) </pre>
Response	This was a flowchart that I produced to put the Wivenhoe strategies into one flowchart. As indicated in my Submission, this was the first attempt to introduce 'predictions' into the selection of the Wivenhoe release strategies. The 'suggestion by DERM' was an attempt to clarify what was intended. There was no such flowchart in Revision 6. I had also realised that some flexibility was needed in the strategy selection in order to pass extreme floods. Once it was discussed more fully with Seqwater, it was agreed that the use of predictions should be accepted.	

No. in Annexure 19	Suggestion by DERM (Annexure 18 and 19 to Statement of Ronald Guppy)	Final version of Seventh Revision of Wivenhoe Flood Mitigation Manual (Exhibit 21)
5	All W strategies should refer to actual levels and flows and not the predicted levels and flows. Then W4A and W4B can be differentiated based on Predicted Maximum Lake Level.	Conditions for Strategy W1, p24: Wivenhoe Storage Level predicted to be less than 68.50 m AHD Conditions for Strategy W2, p27: Wivenhoe Storage Level predicted to be between 68.50 and 74.00 m AHD Conditions for Strategy W3, p28: Wivenhoe Storage Level predicted to be between 68.50 and 74.00 m AHD Conditions for Strategy W4, p29: Wivenhoe Storage Level predicted to exceed 74.00 m AHD Strategy W4A, p29: Lake Level between 74.0 and 75.5 m AHD Strategy W4B, p30: Lake Level greater than 75.5 m AHD
Response	The same comment as in Item 4 applies.	

No. in Annexure 19	Suggestion by DERM (Annexure 18 and 19 to Statement of Ronald Guppy)	Final version of Seventh Revision of Wivenhoe Flood Mitigation Manual (Exhibit 21)
5	I think there needs to be another criterion under Procedures W2 and W3 of not less than 1900 m ³ /s given for the target maximum flows. Otherwise if for example the natural peak flow at Lowood excluding Wivenhoe releases was only 1000 m ³ /s that becomes the target maximum flow there.	No minimum flow rate under Strategy W2 or Strategy W3: p27, 28.
Response	I think this comment has been misconstrued as suggesting that there should be a minimum discharge required under Strategies W2 and W3. It would have been an error to limit discharges under Strategies W2 and W3 because there needs to be flexibility in order to limit downstream damage. E.g. If there is 3000 m ³ /sec coming from the Lockyer and the Bremer, it would be necessary to limit discharges from Wivenhoe to less than 1000 m ³ /sec in order to reduce damages in Brisbane. If the minimum flow was nominated as 1900 m ³ /sec (say) then the flow through Brisbane Engineers who will select the actual discharge depending on what situation is developing. It will be different for each flood event.. The decision to not specify a minimum flow rate was therefore supported.	
5	It may also be useful to specify that the peak outflow should not exceed the peak inflow (i.e the total inflow into Wivenhoe including Somerset outflows).	Not specified in Strategy W2 or Strategy W3: p27, 28. However it is explicitly stated on Page 22.
Response	It is a widely held principal that outflows from a dam should not exceed inflows so that damages are not aggravated by dam operations. It is a principal nearly all dam operators would follow and Seqwater took the view that it did not have to be said. It will be reconsidered for inclusion in Revision 8 of the manual.	

No. in Annexure 19	Suggestion by DERM (Annexure 18 and 19 to Statement of Ronald Guppy)	Final version of Seventh Revision of Wivenhoe Flood Mitigation Manual (Exhibit 21)
7	The inclusion of the large Table in section 8.6 is not necessarily helpful and likely to be confusing. It is only really applicable for the loss of communications strategies. I am happy with the target of getting all the gates open before the first fuse plug triggers but while there are communications with the Flood Operations Centre, the gate opening rates are set by the Flood Operations Engineer. Under normal circumstances, gate operation is not dependent on storage level until EL 74 is exceeded. It is solely based on a discharge. The Table suggests otherwise. Even after EL 74 is reached the strategy is to open gates at minimum intervals until the water level begins to fall. That also is inconsistent with the Table. All that is needed in Section 8.6 is the order of gate operation.	Large table still present in section 8.6, p33, 34, 35.
Response	I believe the Table in the draft version that Mr Guppy was commenting on was different to the one incorporated in the approved version of Revision 7. The version commented on by Mr Guppy nominated headwaters for different gate openings in the left hand column and resultant discharges in column 7. This was obviously an error and Mr Guppy's comment was incorporated by removing these columns from the approved version. The Table is all about the sequencing of gate openings to ensure that the flow in the flip buck is symmetrical and the potential to damage the side walls is limited.	
Two dot points from bottom of document	In the title of the figure on page 40 'Strategy S2' should be removed - it applies to S3 as well.	Title of figure on p40: Strategy S2 – Wivenhoe / Somerset Operating Target Line
Response	Agreed it does apply equally to S3. However, the wording of Strategy S3 does specifically indicate that the requirements for S3 are 'In addition to the operating protocols used in Strategy S2'. It will be reconsidered in Revision 8.	

CTS No. 19928/10

Department of Environment and Resource Management
MINISTERIAL BRIEFING NOTE

TO: Minister for Natural Resources, Mines
and Energy and Minister for Trade

SUBJECT: Dam Emergency Action Plans

REQUESTED BY

- The Minister's Office requested this brief as soon as possible.

TIMEFRAME

- Noting of this brief is required by 10 November 2010 to meet the Minister's request.

RECOMMENDATION

It is recommended that the Minister note that in accordance with his request of 25 October 2010, owners of referable water supply dams have been asked to provide written confirmation that the Emergency Action Plan (EAP) for their dam is current.

BACKGROUND

- This briefing note should be read in conjunction with CTS No. 19311/10 – Managing Flood Impacts Downstream of Large Water Supply Dams approved by the Minister on 25 October 2010 (copy attached).
- A significant number of large water supply dams in Queensland are at, or near, their full capacity. Many catchments are in a 'wetted' condition likely to cause runoff quite readily resulting in water releases from these dams during the coming wet season which runs to about April 2011.
- DERM requires owners of referable water supply dams to have current EAPs.
- The owners of referable water supply dams are required by virtue of the EAPs for their dams to notify local governments responsible for communities downstream of such dams about the volumes of floodwater passing through their dams.

CURRENT ISSUES

- Currently there are 105 referable dams in Queensland.
- By letter dated 25 October 2010, the Minister requested the dam safety regulator, DERM, to seek an assurance from the owners of referable water supply dams that EAPs for their dams are current.
- Wivenhoe Dam, Somerset Dam and North Pine Dam are to be excluded because they are subject to special flood management arrangements.

RESOURCE/IMPLEMENTATION IMPLICATIONS

- There are no resource issues for DERM.

PROPOSED ACTION

- In response to the Minister's request, letters have been sent requiring written confirmation that the EAPs for a total of 69 referable water supply dams are current. This assurance is to be provided to DERM by 30 November 2010.
- The dam owner groups comprise: SunWater – 23 dams; Queensland Bulk Water Supply Authority – 24 dams; DERM owned dams – 5; other owners dams – 18.

Advisor	
Dated	17/11/10
Approved	Not Approved
Further information required	Noted
Minister	
Dated	27/11/10

RECEIVED
MINISTERIAL OFFICE
15 NOV 2010

☐ MINISTER
☐ POL ADV
☐ MEDIA ADV
☐ PARL SEC
☐ ADMIN

Rec'd - ODG

10 NOV 2010

Author Name: John McKenna Position: Manager, DS(FD) Tel No: Date: 5 November 2010	Cleared by Name: Peter Allen Position: Director, Dam Safety Tel No: Name: Bob Reilly Position: GM OWSR Tel No: Date: 7/11/10	Cleared by Name: Chris Robson Position: A/DDO Water & Ecosystem Out Tel No: Date: 9/11/10	Recommended: Name: John Bradley Director-General, DERM Tel No: Date:
--	--	--	---

File Ref:

- No letter is to be sent to the following referable dam owners because:
 - for nine dams, the population at risk is confined to property owned by the dam owner and there is no downstream community that needs to be notified by the relevant local government or emergency management agency in an emergency situation; or
 - the owners of a further 16 dams have informed DERM within the last four months that they have produced/updated or reviewed their EAPs.
- There are 10 referable dams that have no EAPs because:
 - safety condition DS 13 requires an EAP to be prepared by 30 November 2010 for Crystal Waters Estate (Upper and Lower) Dams;
 - construction of Gillens Dam owned by Kupapipi Pastoral Pty Ltd has not yet commenced;
 - Town Dam Lakeland owned by Cook Shire Council is to be modified so that it no longer has a population at risk and therefore will not require an EAP;
 - in the case of the seven referable dams listed in Attachment 1, compliance action has been initiated as the dam owners have failed to produce their EAP by the date required.
- The dam safety regulator, DERM, will monitor compliance with the requirement to supply this information during the first week of December and will implement appropriate follow-up action with any non-compliant dam owner, as necessary.
- A progress report will be provided to the Minister by 15 December 2010.

OTHER INFORMATION

- *Consultation:* N/A
- *Legislation:* N/A
- *Key Communication Messages:* N/A

MINISTER'S COMMENTS

ATTACHMENTS

- Attachment 1 - CTS No. 19311/10

Author Name: John McKenna Position: Manager, DS/ED Tel No: [REDACTED] Date: 5 November 2010	Cleared by Name: Peter Allen Position: Director, Dam Safety Name: Bob Reilly Position: GM OWSR Tel No: [REDACTED]	Cleared by Name: Chris Robson Position: A/DDG Water & Ecosystem Outcomes Tel No: [REDACTED] Date:	Recommended: Name: John Bradley Director-General, DERM Tel No: [REDACTED] Date:
--	---	--	--

Attachment 1

Dam Name	Local Government Area	Dam Owner	Population at Risk
Environmental Dam	Isaac Regional Council	Blair Athol Coal Pty Ltd	3
Forest Lake Dam	Brisbane City Council	Brisbane City Council	218
Gordonbrook Dam	South Burnett Regional Council	South Burnett Regional Council	10
Lake Mitchell Dam	Tablelands Regional Council	Southedge Daintree Pastoral Co Pty Ltd	10
Moody Creek Detention Basin Dam	Cairns Regional council	Cairns Regional Council	73
Springfield Lakes – High Level Dam	Ipswich City Council	Delfin Lend Lease Ltd	70
Springfield Lakes – Low Level Dam	Ipswich City Council	Delfin Lend Lease Ltd	70

2 November 2010

Mr William Steen
Department of Environment and Resource Management
PO Box 1762
ROCKHAMPTON, QLD 4701

Dear William

Re: Notification of EAPs review and update

It is important that emergency response agencies responsible for communities downstream of dams are aware of significant flood events that might pass through the dams or result from events/incidents at the dams so they can mitigate any adverse consequences.

The owners of referable dams are required by the safety conditions applying at their dams to prepare an Emergency Action Plan (EAP) for their dam that will provide such information to those agencies. To be effective this EAP needs to be kept up to date. DS 13 in most instances is the condition relating to EAPs and it contains a requirement to annually advise of the status of the EAP, in particular that it has been reviewed and updated as necessary.

Now as the wet season approaches I am writing to the owners of large dams seeking confirmation that their EAPs have been reviewed and updated as required by the safety conditions to contain current information so that they can be smoothly implemented if necessary.

As the owner of the following dams

Ibis Dam
Copperfield River Gorge Dam
Corella Dam
Crooks Dam
Wyndham Dam

can you please provide confirmation by 30 November 2010 that the EAPs have been updated as necessary in line with the safety conditions.

There are various other notification requirements within the safety conditions. If you have not already done so it would be an opportune time to also provide those required advices.

Street Address
Floor 3 Mineral House, 41 George Street, Brisbane Qld 4000

Postal Address
GPO Box 2454, Brisbane Qld 4001


Telephone [REDACTED]
Facsimile [REDACTED]

Website www.derm.qld.gov.au

ABN 46 640 294 485

Please contact me on [REDACTED] if you have any queries.

Yours sincerely



Peter Allen
Director (Dam Safety)
Office of the Water Supply Regulator

Chief Executive Officer
Toowoomba Regional Council
PO Box 302
TOOWOOMBA, QLD, 4350

Attention Laurie Ashe, Manager Water Infrastructure Assets

Dear Laurie

It is important that emergency response agencies responsible for communities downstream of dams are aware of significant flood events that might pass through the dams or result from events/incidents at the dams so they can mitigate any adverse consequences.

The owners of referable dams are required by the safety conditions applying at their dams to prepare an Emergency Action Plan (EAP) for their dam that will provide such information to those agencies. To be effective this EAP needs to be kept up to date. DS 13 in most instances is the condition relating to EAPs and it contains a requirement to annually advise of the status of the EAP, in particular that it has been reviewed and updated as necessary.

Now as the wet season approaches I am writing to the owners of large dams seeking confirmation that their EAPs have been reviewed and updated as required by the safety conditions to contain current information so that they can be smoothly implemented if necessary.

As the owner of the following dam(s)

Cooby Creek Dam
Cressbrook Creek Dam
Perseverance Creek Dam

can you please provide confirmation by 30 November 2010 that the EAP(s) has been updated as necessary in line with the safety conditions.

There are various other notification requirements within the safety conditions. If you have not already done so it would be an opportune time to also provide those required advices.

Please contact me on [REDACTED] if you have any queries.

Yours sincerely

[REDACTED]
Peter Allen
Director (Dam Safety)
Office of the Water Supply Regulator

Street Address
Floor 3 Mineral House, 41 George Street, Brisbane Qld 4000

Postal Address
GPO Box 2454, Brisbane Qld 4001

Telephone - [REDACTED]
Facsimile - [REDACTED]

Website www.derm.qld.gov.au

ABN 46 640 294 485

Chief Executive Officer
Townsville City Council
PO Box 1268
TOWNSVILLE, QLD, 4810

Attention Rob Hunt

Dear Rob

It is important that emergency response agencies responsible for communities downstream of dams are aware of significant flood events that might pass through the dams or result from events/incidents at the dams so they can mitigate any adverse consequences.

The owners of referable dams are required by the safety conditions applying at their dams to prepare an Emergency Action Plan (EAP) for their dam that will provide such information to those agencies. To be effective this EAP needs to be kept up to date. DS 13 in most instances is the condition relating to EAPs and it contains a requirement to annually advise of the status of the EAP, in particular that it has been reviewed and updated as necessary.

Now as the wet season approaches I am writing to the owners of large dams seeking confirmation that their EAPs have been reviewed and updated as required by the safety conditions to contain current information so that they can be smoothly implemented if necessary.

As the owner of the following dam(s)

Ross River Dam
Paluma Dam

can you please provide confirmation by 30 November 2010 that the EAP(s) has been updated as necessary in line with the Safety conditions.

There are various other notification requirements within the safety conditions. If you have not already done so it would be an opportune time to also provide those required advices.

Please contact me or [REDACTED] if you have any queries.

Yours sincerely

[REDACTED]
Peter Allen
Director (Dam Safety)

Street Address
Floor 3 Mineral House, 41 George Street, Brisbane Qld 4000

Postal Address
GPO Box 2454, Brisbane Qld 4001

Telephone + [REDACTED]
Facsimile + [REDACTED]

Website www.derm.qld.gov.au

ABN 46 640 294 485

Chief Executive Officer
Ipswich City Council
PO Box 191
IPSWICH, QLD, 4305

Attention Quentin Underwood

Dear Quentin

It is important that emergency response agencies responsible for communities downstream of dams are aware of significant flood events that might pass through the dams or result from events/incidents at the dams so they can mitigate any adverse consequences.

The owners of referable dams are required by the safety conditions applying at their dams to prepare an Emergency Action Plan (EAP) for their dam that will provide such information to those agencies. To be effective this EAP needs to be kept up to date. DS 13 in most instances is the condition relating to EAPs and it contains a requirement to annually advise of the status of the EAP, in particular that it has been reviewed and updated as necessary.

Now as the wet season approaches I am writing to the owners of large dams seeking confirmation that their EAPs have been reviewed and updated as required by the safety conditions to contain current information so that they can be smoothly implemented if necessary.

As the owner of the following dams

Marburg Detention Basin

Rosewood Detention Basin

can you please provide confirmation by 30 November 2010 that the EAPs have been updated as necessary in line with the safety conditions.

There are various other notification requirements within the safety conditions. If you have not already done so it would be an opportune time to also provide those required advices.

Please contact me or [REDACTED] if you have any queries.

Yours sincerely

[REDACTED]
Peter Allen
Director (Dam Safety)
Office of the Water Supply Regulator

Street Address
Floor 3 Mineral House, 41 George Street, Brisbane Qld 4000

Postal Address
GPO Box 2454, Brisbane Qld 4001

Telephone + [REDACTED]
Facsimile + [REDACTED]

Website www.derm.qld.gov.au

ABN 46 640 294 485

Chief Executive Officer
Wide Bay Water Corporation
PO Box 5499
HERVEY BAY, QLD, 4655

Attention Denis Heron

Dear Denis

It is important that emergency response agencies responsible for communities downstream of dams are aware of significant flood events that might pass through the dams or result from events/incidents at the dams so they can mitigate any adverse consequences.

The owners of referable dams are required by the safety conditions applying at their dams to prepare an Emergency Action Plan (EAP) for their dam that will provide such information to those agencies. To be effective this EAP needs to be kept up to date. DS 13 in most instances is the condition relating to EAPs and it contains a requirement to annually advise of the status of the EAP, in particular that it has been reviewed and updated as necessary.

Now as the wet season approaches I am writing to the owners of large dams seeking confirmation that their EAPs have been reviewed and updated as required by the safety conditions to contain current information so that they can be smoothly implemented if necessary.

As the owner of the following dams

Eli Creek Effluent Re-use Dam

can you please provide confirmation by 30 November 2010 that the EAPs have been updated as necessary in line with the safety conditions.

There are various other notification requirements within the safety conditions. If you have not already done so it would be an opportune time to also provide those required advices.

Please contact me or [REDACTED] if you have any queries.

Yours sincerely

[REDACTED]
Peter Allen
Director (Dam Safety)
Office of the Water Supply Regulator

Street Address
Floor 3 Mineral House, 41 George Street, Brisbane Qld 4000

Postal Address
GPO Box 2454, Brisbane Qld 4001

Telephone + [REDACTED]
Facsimile + [REDACTED]

Website www.derm.qld.gov.au

ABN 46 640 294 485

Chief Executive Officer
Cairns Regional Council
PO Box 359
CAIRNS, QLD, 4870

Attention Simon Page

Dear Simon

It is important that emergency response agencies responsible for communities downstream of dams are aware of significant flood events that might pass through the dams or result from events/incidents at the dams so they can mitigate any adverse consequences.

The owners of referable dams are required by the safety conditions applying at their dams to prepare an Emergency Action Plan (EAP) for their dam that will provide such information to those agencies. To be effective this EAP needs to be kept up to date. DS 13 in most instances is the condition relating to EAPs and it contains a requirement to annually advise of the status of the EAP, in particular that it has been reviewed and updated as necessary.

Now as the wet season approaches I am writing to the owners of large dams seeking confirmation that their EAPs have been reviewed and updated as required by the safety conditions to contain current information so that they can be smoothly implemented if necessary.

As the owner of the following dam
Copperlode Falls Dam
can you please provide confirmation by 30 November 2010 that the EAP has been updated as necessary in line with the safety conditions.

There are various other notification requirements within the safety conditions. If you have not already done so it would be an opportune time to also provide those required advices.

Please contact me on [REDACTED] if you have any queries.

Yours sincerely

[REDACTED]
Peter Allen
Director (Dam Safety)
Office of the Water Supply Regulator

Street Address
Floor 3 Mineral House, 41 George Street, Brisbane Qld 4000

Postal Address
GPO Box 2454, Brisbane Qld 4001

Telephone [REDACTED]
Facsimile [REDACTED]

Website www.derm.qld.gov.au

ABN 46 640 294 485

Chief Executive Officer
Gold Coast City Council
PO Box 5042
GOLD COAST MIAL CENTRE, QLD, 5042

Attention Edwin Salazar

Dear Edwin

It is important that emergency response agencies responsible for communities downstream of dams are aware of significant flood events that might pass through the dams or result from events/incidents at the dams so they can mitigate any adverse consequences.

The owners of referable dams are required by the safety conditions applying at their dams to prepare an Emergency Action Plan (EAP) for their dam that will provide such information to those agencies. To be effective this EAP needs to be kept up to date. DS 13 in most instances is the condition relating to EAPs and it contains a requirement to annually advise of the status of the EAP, in particular that it has been reviewed and updated as necessary.

Now as the wet season approaches I am writing to the owners of large dams seeking confirmation that their EAPs have been reviewed and updated as required by the safety conditions to contain current information so that they can be smoothly implemented if necessary.

As the owner of the following dams

Tallebudgera Creek Dam
Biggera Creek Flood Detention Basin
Loders Creek Flood Detention Basin

can you please provide confirmation by 30 November 2010 that the EAPs have been updated as necessary in line with the safety conditions.

There are various other notification requirements within the safety conditions. If you have not already done so it would be an opportune time to also provide those required advices.

Please contact me on [REDACTED] if you have any queries.

Yours sincerely

[REDACTED]
Peter Allen
Director (Dam Safety)
Office of the Water Supply Regulator

Street Address
Floor 3 Mineral House, 41 George Street, Brisbane Qld 4000

Postal Address
GPO Box 2454, Brisbane Qld 4001

Telephone + [REDACTED]
Facsimile + [REDACTED]

Website www.derm.qld.gov.au

ABN 46 640 294 485

Chief Executive Officer
Tablelands Regional Council
PO Box 154
MAREEBA, QLD, 4880

Attention Bill Cuthbertson, Manager – Water and Wastewater

Dear Bill

It is important that emergency response agencies responsible for communities downstream of dams are aware of significant flood events that might pass through the dams or result from events/incidents at the dams so they can mitigate any adverse consequences.

The owners of referable dams are required by the safety conditions applying at their dams to prepare an Emergency Action Plan (EAP) for their dam that will provide such information to those agencies. To be effective this EAP needs to be kept up to date. DS 13 in most instances is the condition relating to EAPs and it contains a requirement to annually advise of the status of the EAP, in particular that it has been reviewed and updated as necessary.

Now as the wet season approaches I am writing to the owners of large dams seeking confirmation that their EAPs have been reviewed and updated as required by the safety conditions to contain current information so that they can be smoothly implemented if necessary.

As the owner of the following dam
Wild River Dam

can you please provide confirmation by 30 November 2010 that the EAP has been updated as necessary in line with the safety conditions.

There are various other notification requirements within the safety conditions. If you have not already done so it would be an opportune time to also provide those required advices.

Please contact me on [REDACTED] if you have any queries.

Yours sincerely

[REDACTED]
Peter Allen
Director (Dam Safety)
Office of the Water Supply Regulator

Street Address
Floor 3 Mineral House, 41 George Street, Brisbane Qld 4000

Postal Address
GPO Box 2454, Brisbane Qld 4001

Telephone [REDACTED]
Facsimile [REDACTED]

Website www.derm.qld.gov.au

ABN 46 640 294 485

Chief Executive Officer
Isaac Regional Council
PO Box 229
CLERMONT, QLD, 4721

Attention Andrew McGregor

Dear Andrew

It is important that emergency response agencies responsible for communities downstream of dams are aware of significant flood events that might pass through the dams or result from events/incidents at the dams so they can mitigate any adverse consequences.

The owners of referable dams are required by the safety conditions applying at their dams to prepare an Emergency Action Plan (EAP) for their dam that will provide such information to those agencies. To be effective this EAP needs to be kept up to date. DS 13 in most instances is the condition relating to EAPs and it contains a requirement to annually advise of the status of the EAP, in particular that it has been reviewed and updated as necessary.

Now as the wet season approaches I am writing to the owners of large dams seeking confirmation that their EAPs have been reviewed and updated as required by the safety conditions to contain current information so that they can be smoothly implemented if necessary.

As the owner of the following dam

Theresa Creek Dam

can you please provide confirmation by 30 November 2010 that the EAP has been updated as necessary in line with the safety conditions.

There are various other notification requirements within the safety conditions. If you have not already done so it would be an opportune time to also provide those required advices.

Please contact me on [REDACTED] if you have any queries.

Yours sincerely

[REDACTED]
Peter Allen
Director (Dam Safety)
Office of the Water Supply Regulator

Street Address
Floor 3 Mineral House, 41 George Street, Brisbane Qld 4000

Postal Address
GPO Box 2454, Brisbane Qld 4001

Telephone + [REDACTED]
Facsimile + [REDACTED]

Website www.derm.qld.gov.au

ABN 46 640 294 485

Chief Executive Officer
Southern Downs Regional Council
PO Box 26
WARWICK, QLD, 4370

Attention Jim Llewellyn

Dear Jim

It is important that emergency response agencies responsible for communities downstream of dams are aware of significant flood events that might pass through the dams or result from events/incidents at the dams so they can mitigate any adverse consequences.

The owners of referable dams are required by the safety conditions applying at their dams to prepare an Emergency Action Plan (EAP) for their dam that will provide such information to those agencies. To be effective this EAP needs to be kept up to date. DS 13 in most instances is the condition relating to EAPs and it contains a requirement to annually advise of the status of the EAP, in particular that it has been reviewed and updated as necessary.

Now as the wet season approaches I am writing to the owners of large dams seeking confirmation that their EAPs have been reviewed and updated as required by the safety conditions to contain current information so that they can be smoothly implemented if necessary.

As the owner of the following dam
Connolly Dam

can you please provide confirmation by 30 November 2010 that the EAP has been updated as necessary in line with the safety conditions.

There are various other notification requirements within the safety conditions. If you have not already done so it would be an opportune time to also provide those required advices.

Please contact me on [REDACTED] if you have any queries.

Yours sincerely

[REDACTED]
Peter Allen
Director (Dam Safety)
Office of the Water Supply Regulator

Street Address
Floor 3 Mineral House, 41 George Street, Brisbane Qld 4000

Postal Address
GPO Box 2454, Brisbane Qld 4001

Telephone + [REDACTED]
Facsimile + [REDACTED]

Website www.derm.qld.gov.au

ABN 46 640 294 485

2 November 2010

Mr Mal Halwala
SunWater Limited
PO Box 15536, City East
BRISBANE, QLD 4002

Dear Mal

Re: Notification of EAPs review and update

It is important that emergency response agencies responsible for communities downstream of dams are aware of significant flood events that might pass through the dams or result from events/incidents at the dams so they can mitigate any adverse consequences.

The owners of referable dams are required by the safety conditions applying at their dams to prepare an Emergency Action Plan (EAP) for their dam that will provide such information to those agencies. To be effective this EAP needs to be kept up to date. DS 13 in most instances is the condition relating to EAPs and it contains a requirement to annually advise of the status of the EAP, in particular that it has been reviewed and updated as necessary.

Now as the wet season approaches I am writing to the owners of large dams seeking confirmation that their EAPs have been reviewed and updated as required by the safety conditions to contain current information so that they can be smoothly implemented if necessary.

As the owner of the following dams

Leslie Dam
Bjelke-Petersen Dam
Boondooma Dam
Burdekin Falls Dam
Callide Dam
Cania Dam
Claude Wharton Weir
Coolmunda Dam
Eungella Dam
EJ Beardmore Dam
Fairbairn Dam
Fred Haigh Dam
Julius Dam
Kinchant Dam
Peter Faust Dam
Tinaroo Falls Dam

Street Address
Floor 3 Mineral House, 41 George Street, Brisbane Qld 4000

Postal Address
GPO Box 2454, Brisbane Qld 4001

Telephone - [REDACTED]
Facsimile - [REDACTED]

Website www.derm.qld.gov.au

ABN 46 640 294 485

Wuruma Dam
Kroombit Dam
Teemburra Dam
Paradise Dam
Woongarra Balancing Storage
Moura Offstream Storage
Isis Balancing Storage

can you please provide confirmation by 30 November 2010 that the EAPs have been updated as necessary in line with the safety conditions.

There are various other notification requirements within the safety conditions. If you have not already done so it would be an opportune time to also provide those required advices.

Please contact me on [REDACTED] if you have any queries.

Yours sincerely

[REDACTED]

Peter Allen
Director (Dam Safety)
Office of the Water Supply Regulator

2 November 2010

Mr Peter Borrows
Queensland Bulk Water Supply Authority
PO Box 16146, City East
BRISBANE, QLD 4002

Dear Peter

Re: Notification of EAPs review and update

It is important that emergency response agencies responsible for communities downstream of dams are aware of significant flood events that might pass through the dams or result from events/incidents at the dams so they can mitigate any adverse consequences.

The owners of referable dams are required by the safety conditions applying at their dams to prepare an Emergency Action Plan (EAP) for their dam that will provide such information to those agencies. To be effective this EAP needs to be kept up to date. DS 13 in most instances is the condition relating to EAPs and it contains a requirement to annually advise of the status of the EAP, in particular that it has been reviewed and updated as necessary.

Now as the wet season approaches I am writing to the owners of large dams seeking confirmation that their EAPs have been reviewed and updated as required by the safety conditions to contain current information so that they can be smoothly implemented if necessary.

As the owner of the following dams

Lake MacDonald Dam
Atkinson Dam
Baroon Pocket Dam
Bill Gunn Dam
Borumba Dam
Cedar Pocket Dam
Clarendon Dam
Cooloolabin Dam
Enoggera Dam
Ewen Maddock Dam
Little Nerang Dam

Street Address
Floor 3 Mineral House, 41 George Street, Brisbane Qld 4000

Postal Address
GPO Box 2454, Brisbane Qld 4001

Telephone +
Facsimile +

Website www.derm.qld.gov.au

ABN 46 640 294 485

Maroon Dam
Moogerah Dam
Sideling Creek Dam
Gold Creek Dam
Hinze Dam
Lake Manchester Dam
Leslie Harrison Dam
Poona Dam
Wappa Dam
Bromelton Off-Stream Storage

Can you please provide confirmation by 30 November 2010 that the EAPs have been updated as necessary in line with the safety conditions.

There are various other notification requirements within the safety conditions. If you have not already done so it would be an opportune time to also provide those required advices.

Please contact me on [REDACTED] if you have any queries.

Yours sincerely

[REDACTED]

Peter Allen
Director (Dam Safety)
Office of the Water Supply Regulator

Site Manager
Kareeya Power Station
Stanwell Corporation
c/- GPO Box 773
BRISBANE, QLD, 4001

Kevin Ramm

Dear Kevin

It is important that emergency response agencies responsible for communities downstream of dams are aware of significant flood events that might pass through the dams or result from events/incidents at the dams so they can mitigate any adverse consequences.

The owners of referable dams are required by the safety conditions applying at their dams to prepare an Emergency Action Plan (EAP) for their dam that will provide such information to those agencies. To be effective this EAP needs to be kept up to date. DS 13 in most instances is the condition relating to EAPs and it contains a requirement to annually advise of the status of the EAP, in particular that it has been reviewed and updated as necessary.

Now as the wet season approaches I am writing to the owners of large dams seeking confirmation that their EAPs have been reviewed and updated as required by the safety conditions to contain current information so that they can be smoothly implemented if necessary.

As the owner of the following dam
Koombooloomba Dam
can you please provide confirmation that the EAP has been updated as necessary.

While the safety conditions require the update advice by the end January I would appreciate if you provide the confirmation by 30 November 2010. There are various other notification requirements within the safety conditions. If you have not already done so it would be an opportune time to also provide those required advices.

Please contact me on [REDACTED] if you have any queries.

Yours sincerely

[REDACTED]
Peter Allen
Director (Dam Safety)
Office of the Water Supply Regulator

Street Address
Floor 3 Mineral House, 41 George Street, Brisbane Qld 4000

Postal Address
GPO Box 2454, Brisbane Qld 4001

Telephone + [REDACTED]
Facsimile + [REDACTED]

Website www.derm.qld.gov.au

ABN 46 640 294 485

Wivenhoe Power Station
Tarong Energy Corporation
PO Box 38
FERNVALE, QLD, 4306

Attention Sorin Lupelescu

Dear Sorin

It is important that emergency response agencies responsible for communities downstream of dams are aware of significant flood events that might pass through the dams or result from events/incidents at the dams so they can mitigate any adverse consequences.

The owners of referable dams are required by the safety conditions applying at their dams to prepare an Emergency Action Plan (EAP) for their dam that will provide such information to those agencies. To be effective this EAP needs to be kept up to date. DS 13 in most instances is the condition relating to EAPs and it contains a requirement to annually advise of the status of the EAP, in particular that it has been reviewed and updated as necessary.

Now as the wet season approaches I am writing to the owners of large dams seeking confirmation that their EAPs have been reviewed and updated as required by the safety conditions to contain current information so that they can be smoothly implemented if necessary.

As the owner of the following dam
Splityard Creek Dam

can you please provide confirmation by 30 November 2010 that the EAP has been updated as necessary in line with the safety conditions.

There are various other notification requirements within the safety conditions. If you have not already done so it would be an opportune time to also provide those required advices.

Please contact me on [REDACTED] if you have any queries.

Yours sincerely

[REDACTED]
Peter Allen
Director (Dam Safety)
Office of the Water Supply Regulator

Street Address
Floor 3 Mineral House, 41 George Street, Brisbane Qld 4000

Postal Address
GPO Box 2454, Brisbane Qld 4001

Telephone + [REDACTED]
Facsimile + [REDACTED]

Website www.derm.qld.gov.au

ABN 46 640 294 485

CTS No 22106/10

Department of Environment and Resource Management
MINISTERIAL BRIEFING NOTE

TO: Minister for Natural Resources, Mines
and Energy and Minister for Trade

Advisor	OK
Dated / /	
Approved Not Approved Noted	
Further Information required	
Minister	
Dated / /	

SUBJECT: Dam Emergency Action Plans / Somerset/Wivenhoe Dam Floodwater
Release Protocol

REQUESTED BY

- The Minister's Office requested an update on previous briefing note CTS 19928/10 (copy attached) along with an update on the status of Somerset/Wivenhoe Dam floodwater release protocol

TIMEFRAME

- The MECS due date is 20 December 2010

RECOMMENDATION

It is recommended that the Minister:

- note the status of the Emergency Action Plans for referable dams in Queensland
- note the status of Somerset/Wivenhoe Dam floodwater release protocol

Status of Emergency Action Plans:

BACKGROUND

- This briefing note has been prepared as a follow up to CTS No. 19982/10 – Dam Emergency Action Plans, noted by the Minister on 23 November 2010 (copy attached).
- In accordance with the Minister's request, DERM wrote to referable dam owners seeking confirmation that the Emergency Action Plans for their dams were up to date. This was done so that the potentially impacted local governments responsible for community safety downstream of the dams would be reliably informed of flood situations at the referable dams.
- Currently there are 105 referable dams in Queensland.
- The owners of 80 referable dams were contacted in early November. No letter was sent to the owners of the other 25 dams because:
 - for nine dams, the population at risk is confined to property owned by the dam owner and there is no downstream community that needs to be notified by the relevant local government or emergency management agency in an emergency situation; or
 - the owners of a further 16 dams had informed DERM within the previous four months that they had prepared/updated their EAPs.

CURRENT ISSUES

- Responses have been obtained from the owners of the 80 dams.
- For 65 dams, revised EAPs (or advice that no revision is required) have been received.
- For 1 dam, the due date for provision of an EAP has not yet passed (Environmental Dam at Blair Athol Mine)
- For 1 dam (Town Dam at Lakeland Downs) modification to the works, to make it non-referable, has been completed.
- For the remaining 13 dams the owners have advised of progress in producing or updating

Author Name: Ron Guppy Position: Project Manager, Dam Safety Tel No: [REDACTED] Date: 17 December 2010	Cleared by Name: Peter Allen ✓ Position: Director, Dam Safety Tel No: [REDACTED] Name: Bob Reilly ✓ Position: GM OWSR Tel No: [REDACTED]	Cleared by Name: Debbie Best Position: DDG WEO Tel No: [REDACTED] Name: Dean Ellwood Position: Assistant DG, ENRR Tel No: 3330 5628	Cleared by Name: Terry Wall Position: Assoc DG, OER Tel No: [REDACTED] Name: John Bradley Position: DG, DERM Tel No: [REDACTED]
---	--	---	---

the EAPs. They have all advised dates by which these actions will be completed. Most of the thirteen EAPs should be substantially complete by 31 December 2010 with the others expected to be finalised in January. These dams are listed in Attachment 1.

PROPOSED ACTIONS

- DERM will write to the owners of the remaining 13 dams to confirm the dam owner's nominated date for supply of the EAP. It will state that, unless the EAP is received by the nominated date, compliance action will be initiated, given the issue's importance.
- Initially, compliance action would involve issuing a Show Cause Notice under the *Sustainable Planning Act 2009*, which gives the dam owner 20 business days to respond.
- Issuing the notice now would mean a response would not be required prior to 24 January 2011, by which date, all owners have advised their EAPs will be in place. Therefore, it is not proposed to initiate compliance action now.

Status of Somerset/Wivenhoe Dam floodwater release protocol:

BACKGROUND

- A copy of the draft Protocol was emailed to Brisbane, Ipswich and Somerset Councils on 21 October 2010
- Somerset dam has been included in the draft Protocol because Wivenhoe and Somerset dams are operated on an integrated basis for flood management purposes and Somerset Council would be specifically interested in the operation of Somerset dam;
- A meeting was held on 28 October 2010 between senior staff from Queensland Government agencies and officers from Brisbane and Ipswich City Councils to discuss the draft protocol.
- A positive response has been received from Brisbane City Council
- Somerset and Ipswich Councils have some reservations about wording that they consider may expose council to liability. They continue to consider their position and have yet to reply formally on the issue;
- Department of Community Safety (Emergency Management Queensland), is the lead agency for preparing/finalising the protocol.

CURRENT ISSUES

- The draft protocol was trialled on Sunday 12 December 2010, when advice was received that Wivenhoe would commence releasing water from Monday 13 December.
- The SEQ Water Grid Manager (who leads Queensland Government communications around floodwater releases for these dams) has advised that the draft protocol worked well from a communication and operations perspective.

RESOURCE/IMPLEMENTATION IMPLICATIONS

- There are no resource issues for DERM.

OTHER INFORMATION

- *Consultation:* N/A
- *Legislation:* N/A
- *Key Communication Messages:* N/A

MINISTER'S COMMENTS

Author Name: Ron Guppy Position: Project Manager, Dam Safety Tel No: [REDACTED] Date: 17 December 2010	Cleared by Name: Peter Allen Position: Director, Dam Safety Tel No: [REDACTED] Name: Bob Reilly Position: GM OWSR Tel No: [REDACTED]	Cleared by Name: Debbie Best Position: DDG WEO Tel No: [REDACTED] Name: Dean Ellwood Position: Assistant DG, ENRR Tel No: [REDACTED]	Cleared by Name: Terry Wall Position: Assoc DG, OER [REDACTED] Name: John Bradley Position: DG, DERM [REDACTED]
---	--	--	---

	Dam Name	PAR (1)	Dam Owner	Progress with EAP
1 2 3	Tallebudgera Creek Dam Biggera Creek Detention Basin (2) Loder's Creek Detention Basin	93 2780 255	Gold Coast City Council	EAPs exist for all dams but should be updated. Major changes in council staff responsibilities has resulted in staff inexperienced with dams managing the referable dams. DERM is working closely with newly responsible officers to acquaint them with their responsibilities. This included participation in a trial EAP exercise. The results from the exercises are to be incorporated into the existing EAPs as part of the update now occurring. The owner has advised updated EAPs will be provided by 21 January 2011
4 5	Marburg Detention Basin Rosewood Detention Basin	173 143	Ipswich City Council	Consultant engaged to address various dam safety matters including update of EAP. Update of EAP to receive priority and should be received before the end of January 2011
6	Gordonbrook Dam	10	South Burnett Regional Council	Council advised consultant has been engaged to complete draft EAP by end of December 2010
7 8	Springfield Lakes, Upper Dam Springfield Lakes, Lower Dam	70 82	Delfin Lend Lease (dams located in Ipswich City local government area)	DERM provided comments on a draft EAP provided by owner's consultants. Awaiting formal submission from owner and expected to be received by 20 January 2011
9	Lake Mitchell Dam	9	Southedge Daintree Pastoral Co (dam located in Tablelands local government area)	Owners consultants advised EAP would be provided by 17/12/2010
10	Moody Creek Detention Basin	73	Cairns City Council	Preparation of EAP has commenced but unlikely to be submitted until the end of January 2011
11	Wild River Dam	35	Tablelands Regional Council	Dams manager advised up to date EAP would be provided by 24 December 2010
12	Theresa Creek Dam	12	Isaac Regional Council	Dams manager is updating an existing EAP. Formal response has to go through council processes and is expected by 21/1/11.
13	Crystal Waters Dams	6	Redlands City Council	EAP became due on 30th November 2010. Expected completion before end of January 2011

(1) Population at Risk (PAR) if the dam fails

(2) Detention Basin temporarily store flood waters during major rainfall events. This reduces downstream flooding.

PHA – 29 Current Status of Emergency Action Plans

Dam ID	Dam name	Owner Name	EAP Update requested	EAP Received
22	Middle Creek Dam	Mackay Regional Council	email on 13/10/2010 advising EAP may need to be updated following removal of low wall	7/03/2011
36	Leslie Dam	SunWater Limited	2/11/2010	6/12/2010
43	Tallebudgera Creek Dam	Gold Coast City Council	1/11/2010 Compliance letter sent 10/11/2010	28/05/2008
44	Lake MacDonald Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
96	Ibis Dam	The State of Queensland - Department of Environment & Resource Management	2/11/2010	14/12/2010
174	Leichhardt River Dam	Mount Isa Mines Limited	already submitted	27/05/2010 20/05/2011
210	Atkinson Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
211	Awoonga High Dam	Gladstone Area Water Board		21/02/2011
214	Baroon Pocket Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
217	Bill Gunn Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
219	Bjelke-Petersen Dam	SunWater Limited	2/11/2010	17/12/2010
222	Environmental Dam	Blair Athol Coal Pty Ltd	Compliance action	
227	Boondooma Dam	SunWater Limited	2/11/2010	17/12/2010
228	Borumba Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
235	Bundoora Dam	Anglo Coal (Capcoal Management) P/L	Single PAR	1/06/2011
236	Burdekin Falls Dam	SunWater Limited	2/11/2010	17/12/2010
239	Callide Dam	SunWater Limited	2/11/2010	20/12/2010
242	Cania Dam	SunWater Limited	2/11/2010	20/12/2010
244	Cedar Pocket Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
249	Clarendon Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
252	Connolly Dam	Southern Downs Regional Council	1/11/2010	1/12/2010
253	Cooby Creek Dam	Toowoomba Regional Council	1/11/2010	26/11/2010
254	Coolmunda Dam	SunWater Limited	2/11/2010	17/12/2010
255	Cooloolabin Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
256	Copperfield River Gorge Dam	The State of Queensland - Department of Environment & Resource Management	2/11/2010	10/11/2010

Dam ID	Dam name	Owner Name	EAP Update requested	EAP Received
257	Copperlode Falls Dam	Cairns Regional Council	1/11/2010	Draft by email 22/08/2011
258	Corella Dam	The State of Queensland - Department of Environment & Resource Management	2/11/2010	8/11/2010
259	Cressbrook Creek Dam	Toowoomba Regional Council	1/11/2010	26/11/2010
264	Enoggera Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
266	Eungella Dam	SunWater Limited	2/11/2010	17/12/2010
267	Ewen Maddock Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
268	EJ Beardmore Dam	SunWater Limited	2/11/2010	17/12/2010
269	Fairbairn Dam	SunWater Limited	2/11/2010	6/12/2011
272	Fred Haigh Dam	SunWater Limited	2/11/2010	17/12/2010
278	Glenlyon Dam	Dumaresq-Barwon Border Rivers Commission	August dated letter from Sunwater advising EAP to be reviewed by 22-23 September 2010	13/01/2009
297	Julius Dam	SunWater Limited	2/11/2010	17/12/2010
301	Kinchant Dam	SunWater Limited	2/11/2010	17/12/2010
309	Lenthalls Dam	Wide Bay Water Corporation	Incorrect letter saved in Keeper - unable to locate file to confirm letter was sent on 1/11/2010	15/12/2010
312	Little Nerang Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
318	Maroon Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
323	Moogerah Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
334	North Pine Dam	Queensland Bulk Water Supply Authority	FMM in place	10/11/2010
337	Paluma Dam	Townsville City Council	1/11/2010	15/12/2010
339	Perseverance Creek Dam	Toowoomba Regional Council	1/11/2010	26/11/2010
340	Peter Faust Dam	SunWater Limited	2/11/2010	17/12/2010
344	Ross River Dam	Townsville City Council	1/11/2010	15/12/2010
349	Sideling Creek Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
354	Somerset Dam	Queensland Bulk Water Supply Authority	FMM in place	10/11/2010
356	Storm King Dam	Southern Downs Regional Council	DERM commented on draft EAP on 22/10/2010	1/12/2010
366	Theresa Creek Dam	Isaac Regional Council	1/11/2010	20/01/2011
370	Tinaroo Falls Dam	SunWater Limited	2/11/2010	2/11/2010
377	Wivenhoe Dam	Queensland Bulk Water Supply Authority	FMM in place	10/11/2010
378	Wuruma Dam	SunWater Limited	2/11/2010	17/12/2010

Dam ID	Dam name	Owner Name	EAP Update requested	EAP Received
384	Chinaman Creek Dam	Cloncurry Shire Council	letter from owner on 13/10/2010 advising EAP delay due to other documentation - email requesting update by 30/11/2010 sent on 12/11/2010	28/01/2011
389	Dalrymple Bay Coal Terminal - Quarry Dam	Prime Infrastructure (DBCT) Management Pty Ltd	Single PAR - Dam Safety audit requested update of Crisis & Emergency Mgt Manual to comply with EAP on 8/8/2011	
401	Crooks Dam	The State of Queensland - Department of Environment & Resource Management	2/11/2010	8/11/2010
406	Blackwater Coal Mine - Rockland Creek Dam	South Blackwater Coal Limited (BMA Blackwater Mine)		20/04/2011
416	Perry River Dam	LGL Services Australia Pty Ltd	No DS conditions applied until 2011	Not due yet
476	Gold Creek Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
520	McKinnon Creek Flood Detention Dam	Cairns Regional Council	2003 document received 21-9-2010 - email requesting update by 30/11/2010 sent on 11/11/2010	1/12/2003
521	Lake Mitchell Dam	Southedge Daintree Pastoral Company Pty Ltd	Compliance action	4/01/2011
527	Kroombit Dam	SunWater Limited	2/11/2010	20/12/2010
535	Biggera Creek Flood Detention Basin	Gold Coast City Council	1/11/2010	28/01/2011
634	Eli Creek Effluent Reuse Storage Dam	Wide Bay Water Corporation	1/11/2010	2/12/2010
651	Forest Lake Dam	Brisbane City Council	Compliance action	23/12/2011
654	Gap Creek Dam	Holiday Villages (Aust) Pty Ltd	Single PAR	
657	Gordonbrook Dam	South Burnett Regional Council	Compliance action	Draft 22/12/2010
701	Rifle Creek Dam	Mount Isa Mines Limited	already submitted	27/05/2010 20/05/2011
706	Hinze Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
713	Lake Manchester Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
715	Leslie Harrison Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
730	Poona Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010

Dam ID	Dam name	Owner Name	EAP Update requested	EAP Received
731	Wappa Dam	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
766	Newlands Coal Mine - Cerito Creek Dam	Xstrata Coal Queensland Pty Ltd	Single PAR	7/12/2009
850	Stanwell Power Station - Water Supply Dam	Stanwell Corporation Limited	already submitted	30/06/2010
874	Teemburra Dam	SunWater Limited	2/11/2010	17/12/2010
883	Wyndham Dam	The State of Queensland - Department of Environment & Resource Management	2/11/2010	8/11/2010
1007	Dashwood Property Dam	RP & JC Dashwood	Single PAR	
1198	Wild River Dam	Tablelands Regional Council	1/11/2010	17/12/2007
1350	Russell Property Irrigation Dam	CT, JM, CT & SK Russell	Single PAR	
1450	Splityard Creek Dam	Tarong Energy Corporation Limited	1/11/2010	9/12/2010
1487	Cubbie Station - Top Shed Dam	Cubbie Dirranbandi 1 Pty Ltd	Single PAR	29/04/2011
1491	Tarong Power Station - Cooling Water Dam	Tarong Energy Corporation Limited	Advice of review completed 25/10/2010	24/05/2011
1493	Meandu Creek Dam	Tarong Energy Corporation Limited	Advice of review completed 25/10/2010	24/05/2011
1510	Koombooloomba Dam	Stanwell Corporation Limited	1/11/2010	1/12/2011 Update 22/08/2011
1643	Swanbank Power Station - Cooling Water Dam	CS Energy Ltd	already submitted	03/08/2010 New 08/07/2011
1648	Loders Creek Flood Detention Basin	Gold Coast City Council	1/11/2010	28/01/2011
1755	Andrew Deguara Holdings Pty Ltd Dam	Andrew Deguara Holdings Pty Ltd	Single PAR	
1785	Town Dam - Lakeland	Gary W McClelland	being modified to have no population at risk	Updated FIA being considered
1822	South Walker Mine - Down Dip Dam	BHP Mitsui Coal Pty Ltd	Single PAR	10/01/2011
1826	Kelly's Offstream Storage	Rockhampton Regional Council	already submitted	30/09/2010
1839	Mount Morgan Water Supply - No. 7 Dam	Rockhampton Regional Council	already submitted	30/07/2010
1945	Rosewood Detention Basin	Ipswich City Council	1/11/2010	10/10/2007
1946	Moody Creek Detention Basin Dam	Cairns Regional Council	Compliance action - Compliance notice issued 18/3/2011	22/06/2011
1952	Suhr's Creek Dam	Charters Towers Regional Council	submitted August 2010	4/10/2010
1981	Marburg Detention Basin	Ipswich City Council	1/11/2010	10/10/2007
1997	Paradise Dam	SunWater Limited	2/11/2010	17/12/2010

Dam ID	Dam name	Owner Name	EAP Update requested	EAP Received
2002	Crystal Waters Upper and Lower Dams	Queensland Bulk Water Supply Authority	not requested - EAP not required until 30/11/2010	Draft 31/1/2011
2016	Springfield Lakes - High Level Lake	Delfin Lend Lease	Compliance action	8/04/2011
2031	Woongarra Balancing Storage	SunWater Limited	2/11/2010	17/12/2010
2033	Moura Offstream Storage	SunWater Limited	2/11/2010	17/12/2010
2233	Isis Balancing Storage	SunWater Limited	2/11/2010	17/12/2010
2259	Wyaralong Dam	Queensland Bulk Water Supply Authority	Construction version received April 2010	7/12/2010
2263	Bromelton Off-Stream Storage	Queensland Bulk Water Supply Authority	2/11/2010	10/11/2010
2277	Springfield Lakes - Low Level Lake	Delfin Lend Lease	Compliance action	8/04/2011
2278	Gillens Dam	Kunapipi Pastoral Pty Ltd	Not commenced	