

[REDACTED]

---

**From:** [REDACTED]  
**Sent:** Tuesday, 1 February 2011 9:22 AM  
**To:** [REDACTED]  
**Subject:** Wivenhoe High Rainfall Event

David,

Chronology of notifications made to DERM and SunWater with regard to Splityard Creek Dam condition during the above event:

Monday 10/1/2011, 16:10hrs, attempt to contact SunWater as dam safety engineering consultant - [REDACTED]  
[REDACTED] No contact with anyone, leave answering service messages, no return calls.

Monday 10/1/2011, 16:15hrs, contact DERM [REDACTED] to advise that Splityard Creek Dam is satisfactory.

Tuesday 11/1/2011, 13:55hrs, attempt to contact SunWater [REDACTED] no response.

Tuesday 11/1/2011, 13:55hrs, contact DERM [REDACTED] to advise that inspections of Splityard Creek Dam cannot be carried out due to access road blockages. Discuss the proposal to lower the level in Splityard to EL160.0 to reduce the hydraulic loading as a safety measure in view of the fact that inspections are not being carried out.

Wednesday 12/1/2011, approx. 13:00hrs, contact DERM [REDACTED] (no response from [REDACTED] telephone) to advise that the access to Splityard Creek Dam has been restored, that inspections have recommenced, and that Splityard Creek Dam is satisfactory.

PB then off-site until Friday 14/1/2011, no more contact was made with either SunWater or DERM with regard to the condition of Splityard Creek Dam.

Regards,  
Peter B