

Dear M/s Wilson,

After I had left the Commission of Inquiry I felt that I had failed to properly explain the manner in which water runoff flow to and through my property. The cadastral map provided by the representatives for Bundaberg Regional Council did not fully show the catchment area that affects my property as it did display the hill areas towards the east and on both sides of Smith Crossing Road. The cadastral map indicated that there has been a significant change to the creek caused by water runoff being forced to flow around the dam wall erected near the common fence line to my east. Mention should also be made about those flows through the culvert under the roadway and direct from the roadway through my property.

Barry Underwood,

█ Smiths Crossing Road,

Bucca

11 October 2011



QFCI

Date: 11/10/11 JM

Exhibit Number: 779